

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Artesia
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other		5. Lease Serial No. Multiple--See Attached
2. Name of Operator COG OPERATING LLC Contact: ONETHA B AARON E-Mail: OAARON@CONCHO.COM		6. If Indian, Allottee or Tribe Name
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-818-2319 Fx: 432-221-0858	7. If Unit or CA/Agreement, Name and/or No. NMNM88525X
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Multiple--See Attached		8. Well Name and No. Multiple--See Attached
		9. API Well No. Multiple--See Attached
		10. Field and Pool, or Exploratory BURCH KEELY-GLORIETA-UPPER YE
		11. County or Parish, and State EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	Venting and/or Flaring
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Actual gas flared for this battery for 11/8/13 to 2/8/14 is as follows:

(Permit approval: Electronic Submission #226188)

NOV Total for Battery = 0 mcf
DEC Total for Battery = 0 mcf
JAN Total for Battery = 0 mcf
FEB Total for Battery = 0 mcf

Number of wells flared: (20)

BURCH-KEELY UNIT #411 30-015-36263

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 30 2015

RECEIVED

11/6/15
Accepted for record
NMOCD

14. I hereby certify that the foregoing is true and correct. Electronic Submission #253731 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by CATHY QUEEN on 06/12/2015 (15CQ0282SE)	
Name (Printed/Typed) ONETHA B AARON	Title ENGINEER
Signature (Electronic Submission)	Date 07/18/2014
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved By	Title
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	
Office	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #253731 that would not fit on the form

5. Lease Serial No., continued

NMLC028784B
NMLC028793C

Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	API Number	Location
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 411	30-015-36263-00-S1	Sec 18 T17S R30E Lot 2 1910FNL 990FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 563	30-015-39444-00-S1	Sec 18 T17S R30E NENE 940FNL 330FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 564	30-015-39869-00-S1	Sec 18 T17S R30E Lot 2 1713FNL 355FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 412	30-015-36182-00-S1	Sec 18 T17S R30E SWNE 1940FNL 1363FEL 32.836557 N Lat, 104.007239 W Lon
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 417	30-015-36181-00-S1	Sec 18 T17S R30E SENW 1708FNL 2517FWL 32.837193 N Lat, 104.011426 W Lon
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 548	30-015-39442-00-S1	Sec 18 T17S R29E Lot 1 440FNL 460FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 549	30-015-39522-00-S1	Sec 18 T17S R30E Lot 1 330FNL 1000FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 550	30-015-39523-00-S1	Sec 18 T17S R30E NENW 330FNL 1650FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 552	30-015-39443-00-S1	Sec 18 T17S R30E NENW 1120FNL 2480FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 554	30-015-39755-00-S1	Sec 18 T17S R30E NENE 260FNL 1108FEL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 555	30-015-39566-00-S1	Sec 18 T17S R30E NENE 330FNL 330FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 556	30-015-39907-00-S1	Sec 18 T17S R30E Lot 1 1004FNL 457FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 557	30-015-39316-00-S1	Sec 18 T17S R30E Lot 1 1050FNL 990FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 559	30-015-39317-00-S1	Sec 18 T17S R30E NENW 1120FNL 2480FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 561	30-015-39318-00-S1	Sec 18 T17S R30E NWNE 990FNL 1650FEL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 565	30-015-39568-00-S1	Sec 18 T17S R30E SENE 1650FNL 990FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 566	30-015-39870-00-S1	Sec 18 T17S R30E SENW 1650FNL 1650FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 570	30-015-40267-00-S1	Sec 18 T17S R30E NESE 2310FSL 990FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 572	30-015-40268-00-S1	Sec 18 T17S R30E SENW 2492FNL 2257FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 939H	30-015-39573-00-S1	Sec 18 T17S R30E Lot 1 1152FNL 497FWL

32. Additional remarks, continued

BURCH-KEELY UNIT #412 30-015-36182
BURCH-KEELY UNIT #417 30-015-36181
BURCH-KEELY UNIT #548 30-015-39442
BURCH-KEELY UNIT #549 30-015-39522
BURCH-KEELY UNIT #550 30-015-39523
BURCH-KEELY UNIT #552 30-015-39443
BURCH-KEELY UNIT #554 30-015-39755
BURCH-KEELY UNIT #555 30-015-39566
BURCH-KEELY UNIT #556 30-015-39907
BURCH-KEELY UNIT #557 30-015-39316
BURCH-KEELY UNIT #559 30-015-39317
BURCH-KEELY UNIT #561 30-015-39318
BURCH-KEELY UNIT #563 30-015-39444
BURCH-KEELY UNIT #564 30-015-39869
BURCH-KEELY UNIT #565 30-015-39568
BURCH-KEELY UNIT #566 30-015-39870
BURCH-KEELY UNIT #570 30-015-40267
BURCH-KEELY UNIT #572 30-015-40268
BURCH-KEELY UNIT #939H 30-015-39573

Reason: DCP COMPRESSOR ISSUES