Form 3160-5 (June 2015)

. UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.
LC-065928-A
6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS	
not use this form for proposals to drill <mark>வூர் re-</mark> enter ar	,

Do not use this t abandoned well.	orm for proposals : Use Form 3160-3 (A	to drill of to re-enter an IPD) for such pr GONS	ERVAT	001		
SUBMIT IN TRIPLICATE Other instructions on page 2			TRICT	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well		JUN 0 6	2016	NMNM127486		
☑ Oil Well Gas V		5/2	a	3. Well Name and No.	Littlefield BO Federal #6	
2. Name of Operator OGX Operating, LLC RECEIVED		D	9. API Well No. 30-015-35174			
3a. Address P. O. Box 2064, Midland, Texas 79702		Bb. Phone No. (include area code)		10. Field and Pool or Exploratory Area		
7 . C. Box 2004, Initiality, Toxas 70702		(432) 685-1287	Ì	Brushy Draw Delaware		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			1	11. Country or Parish, State		
Sec. 34, T26S, R29E 423' FSL & 2150' FWL				Eddy County, New Mexico		
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTIC	E, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION		TY	PE OF ACTI	ON		
Notice of Intent	Acidize	Deepen	Produc	ction (Start/Resume)	Water Shut-Off	
. Honce of Intent	Alter Casing	Hydraulic Fracturing	Reclar	nation	Well Integrity	
✓ Subsequent Report	Casing Repair	New Construction	Recom	nplete	1 Other Deepen well	
V Shosequent Report	Change Plans	Plug and Abandon	Tempo	orarily Abandon	Vother Deepen Well below 51/2 CB	
Final Abandonment Notice	Convert to Injection	Plug Back	Water	Disposal		
•	•				60-4 must be filed once testing has been e operator has detennined that the site	
& 45 vis. GIH & commence dri Dual Laterolog, Compensated I rams in BOP to 3 1/2". Run ne	opén hole (7 7/8") & recov lling 4 3/4" hole at 5,110'. Neutron, Gamma Ray froi w 3 1/2", 9.2#, API J-55, t C-12, 5% salt followed by 12.4#/gal. Wt tail in cmt 1	rer large amount of loss circular Drill to 6521'. Final MW 9.55# m 6502', WLTD to 5094'. TIH w JSS Liberty flush joint casing w y 80 sxs Super "C" w/15#/sk po 3.2#/gal. Total 47 bbls of cmt.	tion materia l/gal, Vis 38 w/bit to 6521 n/FS on btm nz, 11#/sx C TOC calcu	al. POOH for downho , Chlorides 82,000 p l'and circulate. POC & FC 1 joint up. Wa SE2, 3/10% C-12, 2	ole motor. Mix mud for 9.0#/gal wt pm. Run open hole logging tool, DH laying down tubing. Change ash down to 6515' TD. Cmt w/65 /10% SMS, 5% salt. Displace w/56	
OPERATOR BEFORT A	STILL R ND PRESSU	HEQUIRE TO RE TEST RESI	SU LLTS	BMIT CO	ompletion the Done	
4. I hereby certify that the foregoing is Steve Douglas	true and correct. Name (Pri	inted/Typed) Engineer Title				
Strupe Donglas	1	Date		05/19/20	16	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THE SPACE FOR FEDERAL OR STATE OFICE USE

Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.