

BREITBURN OPERATING LP
Inspection Violation Corrections (Tony Morales, Inspector)

Well Name and Number	API Number	Inspection Number	Corrective Action / Date
Artesia Unit No. 064	30-015-01784	iTM1618734244 ✓	Staining remediated 08/26/2016
Artesia Unit No. 059	30-015-01792	iTM1618744054 ✓	Location sign correct and visible 08/22/2016
Artesia Unit No. 055	30-015-01798	iTM1618742550 ✓	Power restored/Old drum removed 08/26/2016
Artesia Unit No. 042	30-015-02547	iTM1618740983 ✓	Contaminated material/debris removed 08/26/2016
Dunn B Federal No. 006	30-015-01832	iTM1619047337 ✓	Staining remediated 09/09/2016
Dunn B Federal No. 038	30-015-28244	iTM1619041959 ✓	Wellhead leak repaired/sign correct and visible 08/27/2016
Dunn B Federal No. 046	30-015-28247	iTM1619041171 ✓	Staining remediated 09/12/2016
State 14 C No. 006	30-015-01859	iTM1619336370 ✓	Old tank batteries, treaters, separators removed 09/09/2016
State 14 C No. 009	30-015-01862	iTM1619341267 ✓	Staining remediated 08/25/2016
State 647AC 713 No.121	30-015-01856	iTM1619339930 ✓	Power restored,staining remediated, sign 09/09/2016
Gulf State No. 001	30-015-02024	iTM1619647591 ✓	Staining remediated, old heater tank removed 08/25/2016
State 643 AC 711 No. 87	30-015-02051	iTM1619746762 ✓	Staining remediated 08/15/2016

