

**BREITBURN OPERATING LP**  
**Inspection Violation Corrections (Tony Morales, Inspector)**

| Well Name and Number    | API Number   | Inspection Number | Corrective Action / Date                                    |
|-------------------------|--------------|-------------------|-------------------------------------------------------------|
| Artesia Unit No. 064    | 30-015-01784 | iTM1618734244 ✓   | Staining remediated 08/26/2016                              |
| Artesia Unit No. 059    | 30-015-01792 | iTM1618744054 ✓   | Location sign correct and visible 08/22/2016                |
| Artesia Unit No. 055    | 30-015-01798 | iTM1618742550 ✓   | Power restored/Old drum removed 08/26/2016                  |
| Artesia Unit No. 042    | 30-015-02547 | iTM1618740983 ✓   | Contaminated material/debris removed 08/26/2016             |
| Dunn B Federal No. 006  | 30-015-01832 | iTM1619047337 ✓   | Staining remediated 09/09/2016                              |
| Dunn B Federal No. 038  | 30-015-28244 | iTM1619041959 ✓   | Wellhead leak repaired/sign correct and visible 08/27/2016  |
| Dunn B Federal No. 046  | 30-015-28247 | iTM1619041171 ✓   | Staining remediated 09/12/2016                              |
| State 14 C No. 006      | 30-015-01859 | iTM1619336370 ✓   | Old tank batteries, treaters, separators removed 09/09/2016 |
| State 14 C No. 009      | 30-015-01862 | iTM1619341267 ✓   | Staining remediated 08/25/2016                              |
| State 647AC 713 No.121  | 30-015-01856 | iTM1619339930 ✓   | Power restored,staining remediated, sign 09/09/2016         |
| Gulf State No. 001      | 30-015-02024 | iTM1619647591 ✓   | Staining remediated, old heater tank removed 08/25/2016     |
| State 643 AC 711 No. 87 | 30-015-02051 | iTM1619746762 ✓   | Staining remediated 08/15/2016                              |

