Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	nergy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	ON CONCERNATION DIVIDION	30-015-22560
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sama re, NWI 87303	6. State Oil & Gas Lease No. NM 016788
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Empire Abo Unit (309164)
1. Type of Well: Oil Well Gas Well Other		8. Well Number 192
2. Name of Operator Apache Corporation		9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 1000 Mi	dland, TX 79705	Empire; Abo (22040)
4. Well Location		
Unit Letter J : 220	feet from the South line and 13	90feet from theline
Section 01	Township 18S Range 27E	NMPM County Eddy
	levation (Show whether DR, RKB, RT, GR, etc.	2.)
<u> Parkingan galak dan kepada Paka gabaran dan bahajah dan </u>	3646' GL	
12. Check Approp	oriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENT	TON TO:	BSEQUENT REPORT OF:
	G AND ABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON		
	TIPLE COMPL CASING/CEMEN	NT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER: Re-perforate open in	terval and Acidize [/] OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
	EE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
proposed completion or recomplet		
Apache would like to perform the following wo	ork:	
Producing Interval: 5,754-6,120'		
Objective: re-perforate open interval and acid	ize	
Procedure: (1) POOH with rods and tba. (2) S	can tbg and lay down any worn jts. (3) Rig up v	wireline. (4) Perforate (4spf 60° phasing)
• 5,751-58' • 5,782-87' • 5,790-92' • 5,798-808	8' • 5,810-12' • 5,816-18' • 5,828-40' • 5,852-56	
(5) RIH with RBP and test tbg to 80%. (6)Set (70/30 respectively). (9) RIH with tbg and rod:		Acidize well with 4,000 gallons of 15% and Xyler
Toron respectively). (b) thirt with tog and road	s. (10) Netarri wente production	NW OIL CONSERVATION ARTESIA DISTRICT
		JAN 2 6 2017
Spud Date: 05/30/1978	Rig Release Date: 06/17/1978	The Common of th
<u> </u>		
	The state of the s	11.11.6
I hereby certify that the information above i	s true and complete to the best of my knowled	ge and belief.
()		
SIGNATURE Sabet tusor	TITLE Regulatory Analyst	DATE 01/23/2017
Type or print name Isabel Hudson	E-mail address: lsabel.hudson@a	pachecorp.com PHONE: (432) 818-1142
For State Use Only	D man address.	110112.
	-/ -/ 100	- · · · · · · · · -
APPROVED BY:	TITLE STAFF MANAS	DATE 3-14-17
Conditions of Approval (if any):		

January 21, 2017

Empire ABO Unit # K-192

Legal Name: Empire ABO Unit #192

API # 30-015-22560 Eddy County, NM

Producing Interval: 5,754-6,120'

Objective: re-perforate open interval and acidize

Procedure:

- 1. POOH with rods and tbg
- 2. Scan tbg and lay down any worn jts
- 3. Rig up wireline
- 4. Perforate (4spf 60° phasing)
 - 5,751-58'
 - 5,782-87'
 - 5,790-92'
 - 5,798-808'
 - 5,810-12'
 - 5,816-18'
 - 5,828-40'
 - 5,852-56'
- 5. RIH with RBP and test tbg to 80%
- 6. Set RBP @ 5,880'
- 7. RIH with sonic hammer
- 8. Acidize well with 4,000 gallons of 15% and Xylene (70/30 respectively)
- 9. RIH with tbg and rods
- 10. Return well to production

