Submit 1 Copy To Appropriate District Office State of New Mex Office Energy Minorals and Nature	•
District I – (575) 393-6161 Energy, Minerals and Natural 1625 N. French Dr., Hobbs, NN OIL CONSERVATION	WELL API NO.
District II - (3/3) /48-1283 ADTECTA DISTRICTOR II	20.015.11017
Bit S. First St., Artesia, NM 88210 District III. (505) 334-6178 ARTESIA GETE CONSERVATION.	5. Indicate Type of Lease
District IV = (505) 476-3460 District IV = (505) 476-3460 Santa Fe, NM 874	STATE FEE S
1220 S St. Francis Dr. Santa Fe. NM	6. State Oil & Gas Lease No.
87505 RECEIVED	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	R SUCH
1. Type of Well: Oil Well Gas Well Other	8. Well Number 1H
2. Name of Operator	9. OGRID Number
Black Mountain Operating LLC	371127
3. Address of Operator 500 Main Street Suite 1200, Fort Worth, TX 76102	10. Pool name or Wildcat Purple Sage, Wolfcamp
	Purple Sage, Woncamp
4. Well Location Unit Letter M. (55 feet from the South Line and 100 conference to West Line	
Unit Letter M : 655 feet from the South line and 190 feet from the West line	
Section 9 Township 23S 11. Elevation (Show whether DR,	Range 27E NMPM Eddy County
3146' GL	(KD, K1, GR, etc.)
3.10 33	
12. Check Appropriate Box to Indicate Na	ture of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: Completion Prep Report	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
5/5/17 – MIRU Titan 2" CT Unit. RIH CT, motor, mill. Tag cmt @ 12,070° and wash/drill cmt.	
5/6/17 – Cont. drilling cmt. Tag csg shoe @ 13,942' CTM (csg tally has TD at 13,922'). POOH CT. Establish injection rate through	
shoe. MIRU WL and RIH CBL. Log well and POOH. Show cmt top @ 8,980°. RDMO WL. RDMO CT. WO toe prep.	
5/11/17 – MIRU Elite pumps & API WL. Test iron & WH to 7k. Test good. Open well @ 1250 psi. Open WH and test injection. 2	
bpm @ 3122 psi. Pump 500 bbl acid to clear any remaining cmt stringers from wellbore and flush to TD. RIH WL, plug and guns and	
pump down to depth. Set solid composite bridge plug @ 13,865°. Test plug to 7000 psi. Test good. Perforate stage 1 frac. POOH WL.	
RDMO WL & pump trucks. Shut well in. WO frac.	
Spud Date: Rig Release Date	۵۰
Sput Date.	··
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Thereby covery that you have no above to the best of my knowledge and const.	
SIGNATURE TITLE Open	ations Manager DATE 5/31/2017
The second of the William in the Control of the Con	
Type or print namelohn Wierzowiecki E-mail address:john.wierzowiecki@blackmtn.com PHONE:(817) 698-9901 For State Use Only	
APPROVED BY: DATE 6-6-17	
Conditions of Approval (if any):	