

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-34831
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Read & Stevens, Inc.		6. State Oil & Gas Lease No. K-4538
3. Address of Operator PO Box 1518, Roswell, NM 88202		7. Lease Name or Unit Agreement Name Saragossa 10 State
4. Well Location Unit Letter A : 330 feet from the North line and 990 feet from the East line Section 10 Township 23S Range 26E NMPM County Eddy		8. Well Number 003
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3292' GR		9. OGRID Number 18917
		10. Pool name or Wildcat Happy Valley; Delaware #29665

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: **Add Pay Delaware** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/19-21/17: Swab well. Remove frac treating head. Release pkr. TOH and LD pkr. TIH w/(4) 3/4" bit, sub, and tag at 2620'. NU stripping head, PU swivel and 1 jnt. Clean out to PBTD (TOC) at 2645'. Circ wellbore clean. LD swivel, stripping head. TOH. LD workstring, sub and bit.
7/24/17: TIH w/1 bull plug, (1) 4' perf'd sub, 1 SN, 5 jnts tbg, TAC, 76 jnts tbg, (82 jnts total). Bottom of production string at 2609.54". ND and remove BOP. TIH w/6' gas anchor, (1) 2 1/2" x 1 3/4" x 20' rod insert pump. (103) 3/4" rods w/spray metal couplings, (1) 8' pony sub and (1) 2' x 3/4" pony sub. PU polish rod, repack stuffing box. PU horse head. Hang well on and space out pump. Load tbg w/7 bbls 2% KCL. Run unit and check pump action. Plumb in tbg for flowline to frac tank. Turn well on. RD, and clean location. Well pumping.

NM OIL CONSERVATION
ARTESIA DISTRICT

Spud Date:

6/14/2006

Rig Release Date:

6/17/2006

AUG 11 2017

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE K. Barajas TITLE Production/Regulatory DATE 08/09/17

Type or print name Kelly Barajas E-mail address: kbarajas@read-stevens.com PHONE: 575-624-3760

For State Use Only

APPROVED BY: [Signature] TITLE Staff Mgr DATE 8-14-17

Conditions of Approval (if any):