Form 3160-5 (June 2015)

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NO Do not use this fo abandoned well.	OTICES AND REPOI form for proposals to Use form 3160-3 (API	RTS ON W drill or to re D) for such	e-enter an oroposals.	CD	Arte	NMNM112907 6. If Indian, Allottee	or Tribe	Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agreement, Name and/or No.			
Type of Well ☐ Gas Well ☐ Other				Well Name and No. ROADRUNNER FEDERAL COM 13H					
Name of Operator Contact: MAYTE X REYES COG OPERATING LLC E-Mail: mreyes1@concho.com						9. API Well No. 30-015-44863			
3a. Address 3b. Phone No. 2208 WEST MAIN STREET Ph: 575-74 ARTESIA, NM 88210			o. (include area 48-6945	code) 10. Field and Pool or Exploratory Area COTTONWOOD DRAW; BS			atory Area AW; BS		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					-	11. County or Parish, State			
Sec 25 T25S R26E SESW 210FSL 2025FWL						EDDY COUNTY, NM			
12. CHECK THE APPR	OPRIATE BOX(ES)	TO INDICA	TE NATUR	E OF	NOTICE, 1	REPORT, OR OT	HER I	DATA	
TYPE OF SUBMISSION			TYPE OF ACTION Deepen Production (Start/Resume) Water Shut-Off						
Notice of Intent	☐ Acidize	☐ Dee	epen		☐ Production	on (Start/Resume)	0 7	Water Shut-Off	
	☐ Alter Casing	□ Нус	Iraulic Fracturing		☐ Reclamation		07	Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ Nev	w Construction	n	☐ Recompl	ete		Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plu	and Abandon		☐ Tempora	porarily Abandon			
	☐ Convert to Injection	☐ Plu	☐ Plug Back		☐ Water Disposal				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. COG Operating LLC, respectfully requests to preset the surface casing on the subject wells, the depth, casing, and cement will not change from the originally approved APD. Below is a description of preset operations. Description of Operations 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well. ITIONS OF APPROVAL a. After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations). b. The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used. 2. The wellhead will be installed and tested as soon as the surface casing is cut off and the WOC time has									
	ectronic Submission #4	PERATING L	LC, sent to the	he Carls	sbad	•	T II-AF	RTESIA O.C.D	
Name (Printed/Typed) MAYTE X REYES			Title SE	Title SENIOR REGULATORY ANALYST					
Signature (Electronic Subm				03/201					
	THIS SPACE FO	R FEDERA	AL OR STA	TE OI	FFICE US	E			
Approved By Conditions of approval, if any, are attached. A certify that the applicant holds legal or equitab which would entitle the applicant to conduct of Title 18 U.S.C. Section 1001 and Title 43 U.S.	le title to those rights in the perations thereon.	subject lease	Title Office	CF	neer	ce to any denortment o	ragenov	Date 5/4/2018	

Additional data for EC transaction #413528 that would not fit on the form

32. Additional remarks, continued

been reached.

3. A blind flange at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on the wing valve.

4. Spudder rig operations are expected to take 2-3 days per well on the pad.

5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.

6. Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure

rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.

a. The larger rig will move back onto the location within 90 days from the point at which the wells

are secured and the spudder rig is moved off location.

b. The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set

7. Operaor will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.

8. Once the rig is removed, Operator will secure the wellhead area by placing a 1? steel plate over the cellar and wellhead.

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME:
LEASE NO.:
NMNM112907
WELL NAME & NO.:
SURFACE HOLE FOOTAGE:
BOTTOM HOLE FOOTAGE
LOCATION:
COUNTY:
CO

Potash	♠ None	Secretary	C R-111-P
Cave/Karst Potential	C Low		6 High
Variance	None	Flex Hose	C Other
Wellhead	• Conventional	C Multibowl	
Other	☐4 String Area	☐Capitan Reef	□WIPP

All previous COAs still apply except for the following:

- 1. Operator has proposed to set surface casing with Spudder Rig
 - Notify the BLM when moving in and removing the Spudder Rig.
 - Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
 - BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.