Form 3160-5 (June 2015)

UNITED STATES bl. s.m. DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC064488E

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter at 1 2018 abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

abandoned well. Use form 5100-5 (Al D) for such proposals.							
SUBMIT IN TRIPLICATE - Other instruction STRIEGE ARTESIA O.C.D.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. OTTAWA AOW FED 2		
2. Name of Operator EOG Y RESOURCES INC	.com		9. API Well No. 30-015-28753-00-S1				
3a. Address 3b. Phone No. 104 S 4TH STREET Ph: 575-74 ARTESIA, NM 88210 Fx: 575-74				-	10. Field and Pool or Exploratory Area N DAGGER DRAW		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 3 T19S R25E SWSW 660FSL 660FWL					EDDY COUNTY, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICAT	E NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
	Acidize		Deepen		ion (Start/Resume)	☐ Water Shut-Off	
Notice of Intent ■ Notice of Intent	☐ Alter Casing	☐ Hydr	aulic Fracturing	☐ Reclamation		■ Well Integrity	
		_ •	Construction	☐ Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans		and Abandon	☐ Tempor	arily Abandon		
	☐ Convert to Injection				Disposal		
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. EOG Y Resources, Inc. plans to plug back and recomplete this well as follows: 1. MIRU all safety equipment as needed. 2. POOH with all production equipment. 3. RIH with bit and scraper to 7700 ft. 4. Set a CIBP at 7700 ft with 25 sx Class C cement on top. This will cover top of the Canyon and Canyon perforations. 5. Perforate Wolfcamp 6762 ft - 6830 ft (90). 6. Pump 2 percent KCL water with biocide until pressure breaks over. Max surface treating pressure is 4500 psi. 7. When pressure break occurs, pump 2200g 15% HCL NEFE acid with cationic surfactants with ball sealers at 2.5 bpm. Chase acid with 200 bbls 2 percent KCL water with biocide and cationic							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #382910 verified by the BLM Well Information System For EOG Y RESOURCES INC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 08/07/2017 (17PP0849SE) Name (Printed/Typed) TINA HUERTA Title REGULATORY SPECIALIST						MAY 3 1 2018	
Name (Printed/Typed) TINA HUERTA			Title REGULATORY SPECIALIST "ART			"APITESIA C	
Signature (Electronic Submission)			Date 07/27/2017				
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or			Title Sapv. SET Date				
certify that the applicant holds legal or eq which would entitle the applicant to cond	Office Carhs box						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

Additional data for EC transaction #382910 that would not fit on the form

32. Additional remarks, continued

- surfactants.
 8. Swab well.
 9. Turn well over to production.

Wellbore schematics attached