Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office	y, Minerals and Natural Resources	Revised July 18, 2013
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Γ	WELL API NO.
		30-015-30773
811 S. First St., Artesia, NM 88210	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178	CONSERVATION DIVISION 220 South St. Francis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe NM 87505	
District IV - (505) 476-3460	O.C.D.	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Forstruct II-ARTESIA 87505		B-2017
SUNDRY NOTICES AND R	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL	Samedan State	
DIFFERENT RESERVOIR. USE "APPLICATION FOR F		
PROPOSALS.)		8. Well Number 2
1. Type of Well: Oil Well 🛛 Gas Well [Other	
2. Name of Operator		9. OGRID Number
COG Operating, LLC		229137
3. Address of Operator		10. Pool name or Wildcat
600 W. Illinois Ave, Midland, TX 79701	· · · · ·	Artesia Qn-Grbg-SA
4. Well Location		
Unit Letter 0 : 990 feet	t from the <u>S</u> line and <u>1660</u>	feet from theline
Section 27 Tow	vnship 17S Range 28E	NMPM County Eddy
11. Elevat	ion (Show whether DR, RKB, RT, GR, etc.)	
3670' GR		
	- Dan to Indianto Maturo a CNI (1) - T	Development an Othern Dete
12. Check Appropriate	e Box to Indicate Nature of Notice, F	Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	\boxtimes		
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB			
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM						
OTHER:			OTHER:			
12 Describe proposed or completed operations. (Clearly state all participant details, and give participant dates, including estimated date						

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/25/18 MIRU plugging equipment. ND well head. POH w/ 112 7/8" rods, pump, & 6 K-Bars. Dug out cellar. Circ'd hole w/ brine to kill well. NU BOP. POH w/ 95 jts of 2 7/8" tbg. RIH W/ wireline & tagged 5 ½" CIBP @ 3220'. 06/26/18 Circ'd hole w brine to kill well. Set 5 ½" CIBP @ 2780'. Spotted 25 sx class C cmt @ 2780-2530'. WOC. Tagged plug @ 2750' (notified OCD). Set 5 ½" CIBP @ 2385' (per OCD's request). Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 25 sx class C cmt @ 2385-2135'. WOC. 06/27/18 Tagged plug @ 2132'. Spotted 25 sx class C cmt @ 850-600'. WOC. Tagged plug @ 598'. Perf'd csg @ 585'. ND BOP. Sqz'd 120 sx class C cmt @ 585' & circulated to surface. Rigged down and moved off. 07/03/18 Moved in backhoe and welder. Dug out cellar. Verified cmt to surface. Cut off well head. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.

Spud Date:	Rig Release Date:		
I hereby certify that the information above is true an SIGNATURE	^	ledge and belief. <u>1/1/2017</u> DATE_ <u>7/1/2/1</u> DATE_ <u>7/1/2/1/</u> DATE_ <u>7/1/2/1/2</u>	8 5-4 <u>33</u> 2
APPROVED BY: APPROVED BY: Conditions of Approval (if any):		DATE 7-18-18	8