Form 3160-5 (June 2015)

. ITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

DAPAGO, JULIA
Lease Serial No.
NINANINAA AO AE

SUNDKY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter an	,
	Una form 2460 2 (ADD) for such annual	_

001451(1	1						
Do not use thi abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well Oil Well Gas Well Oth	8. Well Name and No. LEONARD FEDERAL 4						
Name of Operator BREITBURN OPERATING LF		9. API Well No. 30-015-03218-00-S1					
3a. Address 1111 BAGBY STREET SUITE HOUSTON, TX 77002	1600	. (include area code) 2-8730		10. Field and Pool or Exploratory Area GRAYBURG			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description))			11. County or Parish, State		
Sec 33 T17S R29E NWNW 99		EDDY COUNTY, NM					
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	FNOTICE	E, REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize ☐ D		eepen 🔲 I		ction (Start/Resume)	■ Water Shut-O)ff
-	☐ Alter Casing	🗀 Hyd	raulic Fracturing	☐ Reclar	mation	■ Well Integrity	/
Subsequent Report	□ Casing Repair	☐ New	Construction	☐ Recom	nplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	🔀 Plug	and Abandon	☐ Tempo	orarily Abandon		
·	☐ Convert to Injection	Plug	Back	■ Water	Disposal		
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Aldetermined that the site is ready for fine Breitburn Operating LP receiv P&A was completed as follows:	operations. If the operation respondent Notices must be file in all inspection. ed approval to P&A this was a second or secon	sults in a multipl ed only after all	e completion or reco requirements, includ	mpletion in a	a new interval, a Form 316 on, have been completed a	0-4 must be filed onc	
6-15-2018: MIRUPU, bleed we	ell down, unseat pump, Po	OOH and LD	rods and pump				
6-18-2018: POOH and LD tub	ing. RIH with 5.5 14# <u>CIE</u>	BP and set @	2400' and dump	ed cement	1120	LAMATIO	- •
7-18-2018: MIRU shut down DUE 1-23-							
7-19-2018: NDWH, NU BOP F brine mixed w/15 sks gel. Circ	POOH & LD 70 units prod c MUD to surface.	Ġ	2400'. RI		NM OIL AR	CONSERVAT	MOI
14. I hereby certify that the foregoing is	Electronic Submission #4	RN OPERATIN	G LP, sent to the	Carlsbad	•	RECEIVED	
Name (Printed/Typed) CHARLO	ITE NASH		Title REGUL	ATORY			
Signature (Electronic S	Submission)		Date 08/07/20	018	ACCEPTED FO	R RECORD	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE	JSE		
Approved By		·	Title		AUG - 8	201 8 _{Date}	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent to condu	itable title to those rights in the		Office		BUREAU OF LAND A	MANAGEMENT	
Fitle 18 U.S.C. Section 1001 and Title 43				willfully to r	CHINES HILL	'U UI 1 UL	

Additional data for EC transaction #430209 that would not fit on the form

32. Additional remarks, continued

7-20-2018: Circ w/42 bbls brine gel, mix & spot 25 sks cement on top of CIBP @ 2400'. Set packer @ 281' test casing to 300#. Test good. bleed of pressure, MIRU WL, RIH & Perf casing @ 806'. POOH WWL., RU & break circulation thru perfs & 8 5/8". inj rate 1.5 BPM, squeeze perfs w/ 100 sks C cement & displace to 706'. Close well in & WOC, SD

7-23-2018 RIH & tag cement @ 670'. BLM on location, approved tag, POOH w/tbg & packer, MIRU WL, RIH & perf casing at 400' est pump in rate of 2 bpm & have circ to surface, mix & squeeze perfs w/ 100 sks cement. circ cement out 8 5/8 & 5 1/2 casing. fill casing up to surface inside and out. Close well in and SDFN. Well is P&A

7-24-2018:) Open well & verify that cement is at the surface, BLM witnessed, OK'd RDPU & plugging equipment. Move off of location, plugging is complete, clean up location. Cut off well head, cut off anchors, flush flowline & move out. Begin remediation of the location.

Final abandonment notice to follow.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612