

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
220 South St. Francis Dr.
Santa Fe, NM 87505
DISTRICT II-ARTESIA O.C.D.

Form C-103
Revised July 18, 2013

WELL API NO. 30-015-02414	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name State	
8. Well Number 001	
9. OGRID Number 024188	
10. Pool name or Wildcat 73570 Burton; Yates, South (gas)	
4. Well Location Unit Letter M. 659 feet from the south line and 661 feet from the west line Section 21 Township 20S Range 28E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3236-ft GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plugging and Abandonment: The plugging and abandonment was accomplished in two phases. Phase 1 was conducted in February 2018, where the packer was removed. Phase 2 was conducted in July, where the well was plugged with cement from the bottom to the surface.

Phase 1

- (1) 2/6/2018, moved onto the well, killed with freshwater
- (2) Released Packer (AD1) and pulled out of hole. The amount of tubing was correct.

Phase 2

- (3) 7/25/18 Tripped in hole with open ended tubing to top of cement
- (4) Start pumping cement as tubing is pulled. The tubing will stay in the cement. Cement to surface. Used 8 yards of cement.
- (5) Wait on Cement. Cement did not fall.
- (6) Cut off well head, weld on plate, and install P&A marker (with well information)
- (7) Clean up and level location as required

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Maley TITLE President DATE 8-22-18
Type or print name David Maley E-mail address: Dmaley@visionresources.com PHONE: 575-361-6601
For State Use Only

APPROVED BY: Staff TITLE Staff DATE 8-31-18
Conditions of Approval (if any):