Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 Revised March 25, 1999	
District I* Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.		
District II	OIL CONSERVATION DIVISION		30-005-63551	
811 South First, Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505		STATE X FEE 6. State Oil & Gas Lease No.		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & G VA-2015	as Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Lavatta DDO Stata Com	
PROPOSALS.)			Loretta BBO State Com	
1. Type of Well:				
Oil Well Gas Well X Other 2. Name of Operator			8. Well No.	
Yates Petroleum Corpor	ation (a)	*	2	
3 Address of Operator (V VIII) 2000 Co.			9. Pool name or	Wildcat
1 1050 11 111 01 1 1 1 1 1 1 1 1 1 1 1 1			Wildcat Precambrian	
		RECEIVED ARTESIA CD - ARTESIA	<u> </u>	
4. Well Location				
Unit Letter G: 1980 feet from the North Co., line and 1980 feet from the East line				
Unit Letter G: 1980 feet from the North of the line and 1980 feet from the East line				
Section 19	Township 10S Ra	nge 27E	NMPM C	Chaves County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3739'GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K 🗆	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR		PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AI	ND	
OTHER:		OTHER: Compl	etion Operations	X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
6/11/03 – Perforate Silurian 6310'-6314' (16), 6316'-6324' (32), 6328'-6336' (32) for a total of 80 holes.				
6/12/03 – Acidize Silurian with 1000g 20% IC acid. 6/16/03 – Perforate Wolfcamp 5734'-5741' for a total of 38 holes. Set RBP at 5850'. Set packer at 5654'.				
6/17/03 – Renorate Wollcamp 5/34 - 5/41 for a total of 38 holes. Set ker at 5850 . Set packer at 5654 . 6/17/03 – Acidize Wolfcamp with 700g 20% IC acid and 49 balls.				
o, 17700 Metales Well-camp Will 700g 2070 To dela dita 47 balls.				
\cdot				
,				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print name Tina Huerts			Telephone No. 50	
(This space for State use)		0		J
	v W. Sum TITLE	Westreet:	Sigewisor	JUL 0 1 2003
Conditions of approval, if any:	111LL			