

RECEIVED

Form 3160-5 (March 2012)

NOV 05 2018

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. NMLC029342A
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well [X] Oil Well [] Gas Well [] Other

8. Well Name and No. Woolley Federal #1

2. Name of Operator COG Operating LLC

9. API Well No. 30-015-04369

3a. Address 600 W Illinois Midland TX 79701

3b. Phone No. (include area code) 432-683-7443

10. Field and Pool, or Exploratory Area Loco Hills-QU-GRBG-SA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 21, T17S R30E SWSW 660'FSL 660'FWL

11. County or Parish, State Eddy

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

Table with columns TYPE OF SUBMISSION and TYPE OF ACTION. Includes checkboxes for Notice of Intent, Subsequent Report, Final Abandonment Notice, Acidize, Deepen, Production (Start/Resume), Water Shut-Off, etc.

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

10/02/18 MIRU Plugging equipment. Unseated pump. POH w/ 81 Fiber glass rods, 97 - 7/8" rods, 27 K-Bars & pump. Dug out cellar. ND well head, NU BOP. 10/03/18 Tagged existing 5 1/2" CIBP @ 6480'. Set 5 1/2" CIBP @ 4550'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Perf'd csg @ 4545'. Pressured up on perfs to 1000 psi. Spotted 25 sx cmt @ 4550-4297'. WOC. 10/04/18 Tagged plug @ 4334'. Perf'd csg @ 4053'. Pressured up on perfs to 1000 psi. Spotted 30 sx class C cmt 2/ 2% CACL @ 4122-3819'. WOC. Tagged plug @ 3739'. Perf'd csg @ 3220'. Pressured up on perfs. Spotted 30 sx class C cmt @ 3278-2975'. WOC. 10/05/18 Tagged plug @ 2996'. Perf'd csg @ 1135'. Loaded hole, pumped into perfs @ 1/2 bbl per minute @ 1800-1400 psi. Spotted 35 sx class C cmt @ 1201-847' (Per Jim Amos w/ BLM's request). WOC. 10/08/18 Tagged plug @ 847'. Perf'd csg @ 545'. ND BOP. Squeezed 125 sx class C cmt @ 545' & circulated to surface. Rigged down & moved off. 10/12/18 Moved in backhoe and welder. Dug out cellar. Verified cmt to surface. Cut off well head. Welded on "Below Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.

RECLAMATION PROCEDURE ATTACHED

GC 11-7-18 Accepted for record NMOCD

ENTERED stamp

RECLAMATION DUE 4-8-'19

ENTERED stamp 10/19/18

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Title Operations Engineering Tech Signature Alette Aaron Date 10/16/18

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD stamp with date NOV 1 2018 and BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

Approved by Title Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Petroleum Engineering Tech
575-234-5909, 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230

Henryetta Price
Environmental Protection Specialist
575-234-5951

Shelly Tucker
Environmental Protection Specialist
575-234-5979

Trishia Bad Bear, Hobbs Field Station
Natural Resource Specialist
575-393-3612