Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 87240  A Sphergy, Minerals and Natural Resources	Revised March 25, 1999 WELL API NO.
District II 811 South First, Artesia, NM 87210  OIL CONSERVATION DIVISION	30-015-32559  5. Indicate Type of Lease
811 South First, Artesia, NM 87210  District III  1000 Rio Brazos Rd., Aztee NM 874 RECEIVED  District IV  OIL GONSERVATION DIVISION  2003  2040 South Pacheco  Santa Fe, NM 87505	STATE X FEE
District IV 2040 South Pacheco, Santa Se, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:  Oil Well  Gas Well  X Other	7. Lease Name or Unit Agreement Name State "IE" Com
2. Name of Operator Ricks Exploration, Inc.	8. Well No. 3
3. Address of Operator 550 W. Texas Ave, Suite 1300 Midland, Texas 79701	9. Pool name or Wildcat Happy Valley; Morrow Gas
4. Well Location	
Unit Letter D: 829 feet from the North line and '363 feet from the West line	
Section 16 Township 22S Range 26E	NMPM County Eddy
10. Elevation (Show whether DR, RKB, RT, G	R, etc.)
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND	
	ABANDONMENT TEST AND X
OTHER: OTHER:	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.</li> <li>5-12-03 Spud 17 1/2" hole @ 1:45 AM 5/12/03</li> <li>5-17-03 Ran 17 jts. 13 3/8" 48# H-40 STC csg set @ 734'. Ran 5 centralizers. Cmt'd w/lead #1: 200 sx H + 10% A-10 + 10# Gilsonite + 1% CaCl2 + 1/4# CF &amp; lead #2: 400 sx 35/65 Poz + 6% gel + 2% CaCl2 + 5# Gilsonite + 1/4# CF. Tailed w/200 sx C + 2% CaCl2. Cmt. did not circulate. Temp survey @ 425'. 1" w/450 sx C + 2% CaCl2. Circ 20 sx to surface. WOC 24 hrs. Tested to 1200 psi - ok.</li> <li>5-24-03 In 12 1/4" hole, ran 54 jts. 9 5/8" 40# J-55 L%&amp;C csg. set @ 2315'. Ran 8 centralizers. BJ cmt'd w/lead 1: 400 sx H + 10% A-10 + 10# Gilsonite + 1% CaCl &amp; lead 2: 510 sx 50/50/10-C + 5% salt + 1/4 PPS CF + 5# Gilsonite &amp; tailed w/200 sx C + 2% CaCl. Plug down @ 6:12 PM MDT 5/22/03.</li> <li>5-25-03 1" to surf w/150 sx Cl C + CaCl2 (2 1/2), WOC 21 hrs. Tested to 2000# - ok.</li> <li>6-22-03 In 8 3/4" hole, ran 274 jts. 5 1/2" 17# LT&amp;C S-95 csg. set @ 11,750'. Ran 25 centralizers. Pumped 500 gals Mud Clean II ahead of cmt. BJ cmt'd w/920 sx 50/50 sx H + .5% FL-52 + .5% FL-25 + 2% SMS + 5% salt + 3#/sx Gilsonite. Floats held. Plug down @ 11:30 PM MDT 6/21/03.</li> <li>6-23-03 Released rig @ 10 AM 6/22/03. SWI waiting on completion unit.</li> </ol>	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  Type or print name Brenda Coffman  Telephone No.	
(This space for state use)  APPROVED BY  Conditions of approval, if any:  APPROVED BY  TITLE  DATE  DATE	