(June 2015) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2					OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM59386 6. If Indian, Allottee or Tribe Name		
					7. If Unit or CA/Agreement, Name and/		
					1. Type of Well Gas Well Other		
2. Name of Operator OXY USA INCORPORATED Contact: DAVID STEV E-Mail: david_stewart@oxy.com			WART 9		9. API Well No. 30-015-29882-00-S1		
3a. Address 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521		3b. Phone No. (include area code) Ph: 432.685.5717			10. Field and Pool or Exploratory Area E PIERCE CROSSING		
4. Location of Well (Footage, Sec., T., R., M., or Survey Descrip		ion)			11. County or Parish, State		
Sec 25 T24S R29E SWSW 860FSL 860FWL						EDDY COUNTY, NM	
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, C	R OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
□ Notice of Intent	Acidize		Deepen Pro		uction (Start/Resume) Ukater Sh		
Subsequent Report	Alter Casing		Iraulic Fracturing	🗖 Reclama		🗋 Well In	
Final Abandonment Notice	Casing Repair Change Plans	_	v Construction	Recomp		🗖 Other	
T mai Abandonment Nonce	Convert to Injection		g and Abandon g Back	U Tempora	arily Abandon	I	
5/21/19 - Unseat pump, POOF 5/22/19 - NDWH, attempt to pu locate 13-3/8".		vork on WH. v	alve Dig out cella	ar trying to		ATTACHE	
5/23/19 - Work stuck tbg, get to dragging/hanging up.	hru flange, set slips, ND	flange, NU B	OP. Start to POC	DH w/ tbg, T	AC	RECLAMA DUE /2-3-	
5/28/19 - Continue to POOH w POOH, <u>BLM witnessed.</u> RIH v	/ tbg. RIH w/ gauge ring v/ tbg & tag CIBP @ 794	to 7950', PC	OH. <u>RIH & set C</u> // 10# MLF, test <u>c</u>	<u>) IBP @ 794(sg to 500#,</u>)' tested	RECEIVED	
						<u> </u>	
14. I hereby certify that the foregoing is	Electronic Submission #				•		
Commi Name(Printed/Typed) DAVID ST	tted to AFMSS for proces	sing by DEBO	RAH MCKINNEY of Title REGUL	on 06/05 <u>/2019</u>			
				AU	CEPIED	FOR RECOR	
	ubmission)		Date 06/05/20		JUN	- 6 2019	
Signature (Electronic S				OFFIGE US		· 2013	
Signature (Electronic S	THIS SPACE F	OR FEDERA			+		
		OR FEDERA	L OR STATE		UREAU OF LA	AND MANAGEMENT	
Approved By	THIS SPACE F	s not warrant or			UREAU OF LA		
Approved By onditions of approval, if any, are attached ertify that the applicant holds legal or equ which would entitle the applicant to conduc	THIS SPACE For Approval of this notice does itable title to those rights in the ct operations thereon.	s not warrant or e subject lease	Title Office	B	American UREAU OF LA CARLSBAL	AND MANAGEMENT D FIELD OFFICE	
Approved By Conditions of approval, if any, are attached ertify that the applicant holds legal or equ which would entitle the applicant to conduc	THIS SPACE F(s not warrant or e subject lease	Title Office	B	American UREAU OF LA CARLSBAL	AND MANAGEMENT D FIELD OFFICE	
Approved By Conditions of approval, if any, are attached sertify that the applicant holds legal or equ which would entitle the applicant to conduc Fitle 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent so Instructions on page 2)	THIS SPACE F(5 not warrant or e subject lease crime for any pr s to any matter w	Title Office erson knowingly and ithin its jurisdiction.	B willfully to ma	UREAU OF LA CARLSBAL	AND MANAGEMENT D FIELD OFFICE tunent or agency of the U	

Additional data for EC transaction #467696 that would not fit on the form

32. Additional remarks, continued

good. M&P 25sx CI H cmt, Calc TOC 7737', PUH.

5/29/19 - <u>RIH to 7121', M&P 25sx CI H cmt, PUH, WOC</u>. RIH & tag cmt @ 6883'. <u>PUH to 5475', M&P 25sx CI C cmt, PUH, WOC</u>.

5/30/19 - RIH & tag cmt @ 5210'_BLM notified. PUH to 4241'. M&P 25sx CI C cmt, PUH, WOC__RIH & tag cmt @ 3937', PUH & set pkr @ 2880', RIH & perf @ 3270', EIR @ 1.5bpm @ 800# w/ full circ out 5-1/2" X 8-5/8" annulus. M&P 45sx CI C cmt, PUH, WOC.

5/31/19 - <u>RIH & tag cmt @ 3115'_Netified BLM</u>, PUH & set pkr @ 2627', RIH & perf @ 3065', EIR @ 1.5bpm @ 1000# w/ circ out 5-1/2" X 8-5/8" annulus. M&P 45sx CLC cmt, PUH, WOC, RIH & tag cmt @ 2900', <u>Notified BLM</u>, PUH & set pkr.@ 443', RIH & perf @ 1005', EIR @ 2bpm @ 500# w/ circ out 5-1/2" X 8-5/8" annulus, <u>M&P 90sx C</u>I C cmt, WOC.

6/3/19 RIH & tag cmt @ 672'_notified BLM_PUH & set pkr @ 31'_RIH & perf @ 405'_EIR @ 2bpm @ 500#_w/ circ out 5-1/2" X 8-5/8" annulus. Rel pkr, POOH, ND BOP NE flange, M&P 120sx CL C cmt, circ cmt to surface. Verify cmt to surf on all csg. RD PU. Carlsbad, New Mexico 88220-6292 תנת/gov.mid.gov



IAKE PRIDE

MERICA

14

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure) Strip and remove callche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Bairicade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area

- The Application for Permit to Drill or Reenter (APD Form 3160-3), Surface Use Plan of ì Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- For wells and/or access roads not having an approved plan, or an inadequate plan for surface 2 reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3, 60-4) For final "eclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3) 60-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the 3
- 4. Previous instruction had you waiting for a BLM specialist to inspect the ocation and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice you are free to proceed with reclamation as per approved APD. If you

Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.

6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.

7 At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Eviironmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612