5

Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Oil Cons. N.M. DIV-Dist. 2 1301 W. Grand Avenue Artesia, NM 88210

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 200

LC-067136

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an

Expires January 31, 2004

5. Lease Serial No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.		
							Type of Well
Oil Well Gas Well X Other P&A				8. Well Name and	8. Well Name and No.		
2. Name of Operator				Scout EH Fe	Scout EH Federal #4		
Yates Petroleum Corporation				9. API Well No.	-		
3a. Address 3b. Phone No. (include area code)				30-015-2297	2		
105 S. 4th Str., Artesia, NN	505 <i>-748</i>	1471,003	10. Field and Pool	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M.	1	ARTEO	~ /	Penasco Draw Morrow			
		ARTESIA E		11. County or Parish, State			
1980'FSL and 660'FWL of Section 27-T18S-R25E				Eddy County	Eddy County, New Mexico		
12. CHECK APPROP	RIATE BOX(ES) TO		000		THER DATA		
TYPE OF SUBMISSION			TYPE OF ACT	ION			
	Acidize	Deepen	Pr	oduction (Start/Resume)	Water Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat	Re	clamation	Well Integrity		
[]	Casing Repair	New Construc	rion Re	complete	Other		
Subsequent Report		<u> </u>					
	Change Plans	X Plug and Abar	ndon Te	mporarily Abandon	Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	\square w	ater Disposal			
testing has been completed. Final Abandor determined that the site is ready for final insp. Went in and fixed parted tubir at 2222'. Established injection Dumped 129' cement on top of Set 475 sx "C" cement plug at tagged at 4166'. Tubing plug from 4166'-3990'. POH with 54 joints 4-1/2" casing. LD 6 wellhead and BOP. RIH with 2224'. POH with 35 stands. and tag at 1016'. Spot 60 sx Clean location. Release all re 6/11/03 - PLUGGED AND AB	ng and bad casing to n rate of 1.5BPM at of retainer. Perforate nd dumped 129' cer ged. RIH and circula 35 stands 2-3/8" tubi joints 3-3/4" washpil 71 joints 2-3/8" to 2 RIH and tag at 2164 "C" neat at 460'-360 ental equipment. Cu	o prepare to plug at 1800# below retate 4 squeeze holes ate brine mud from the pe, 6 4-1/8" DC's, 261'. Spot 60 sx "C" ND BOP and wat off wellhead and REPORT.	and abandon iner at 8045'. s at 5900'. Se ainer. TOC a m 4166'-2200 d wellhead. P 6 3-1/8" DC's "C" with additives wellhead. Spod install dry ho	this well. Spliced an Squeeze with 60 steet retainer on wireling t 4000' behind 4-1/2'. Spotted 60 sx. "C U 4-1/2" casing with a and 64 joints 2-7/8 ives across 4-1/2" cas at 1158'-1050'. West 25 sx. "C" neat from the marker.	nd pulled casing x "H" with additives e at 5850'. " casing. RIH and "cement a spear and LD " tubing. NU asing stub at ait 2 hrs. RIH m surface to 60'.		
14. I hereby certify that the foregoing is the Name (Printed/Typed)	11	iability under bond i	s retained una	1 1			
Tala H	uerta s	orface restoration is	Regulatory C	ompliance Supervis	2003 I		
Signature	hurta	Date	July 7, 2003		DVAK		
	THIS SPACE	FOR FEDERAL OR	STATE OFFICE	USE PETROLEUN	MENGINEER		
Approved by			Title	Date		\	
Conditions of approval, if any, are attache certify that the applicant holds legal or ed which would entitle the applicant to conductions.	quitable title to those rights operations thereon.	in the subject lease	Office				
Title 18 U.S.C. Section 1001 and Title 43 U.States any false, fictitious or fraudulent sta				lly to make to any departmen	nt or agency of the United		