Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FEB 0 5 2020

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

NMNM43744

	SUNDRY	NOTICES	AND	REPO	DRTS	ON	WELLS	5
n -								1

Do not use this form for proposals to drill or to se extended to the season of the sea

	000 ioim 0100-0 (Ai	D) TOT SUMMERING	dorden Co	- 8 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		
SUBMIT IN	TRIPLICATE - Other ins	tructions on pa	ge 2		7. If Unit or CA/Agree	ement, Name and/or No.
Type of Well	ner				8. Well Name and No. MultipleSee Atta	ched
2. Name of Operator OXY USA INCORPORATED	Contact: E-Mail: LESLIE_R	LESLIE REEVE EEVES@OXY.CO	S M	-,	9. API Well No. MultipleSee At	tached
3a. Address 5 GREENWAY PLAZA SUITE HOUSTON, TX 77046-0521	110					
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description	j			11. County or Parish, S	State
MultipleSee Attached					EDDY COUNTY	, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE	NATURE OI	F NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
☑ Notice of Intent	☐ Acidize	-		☐ Product	ion (Start/Resume)	□ Water Shut-Off
□ Subsequent Report	_	-	_	☐ Reclama	ation	■ Well Integrity
						Other
☐ Final Abandonment Notice	_	_		☐ Tempor	arily Abandon	PD
				_	-	
testing has been completed. Final Abdetermined that the site is ready for fit OXY USA INC. respectfully retwo wells listed below. Also, pland Bradenhead CBL variance Platinum MDP1 34-3 Federal CPlatinum MDP1 34-3 Federal C	andonment Notices must be file in a linspection. quests to amend the casing ease note the addition of exercises. Com 25H - 30-015-46558 Com 26H - 30-015-46559	ng design, ceme the BOP Break (8864'TVD) (8954'TVD)	crements, including and mucresting, offline	ng reclamation d programs e cementing TISDA Oper	n, have been completed and for the definition of the desired of the desired of the definition of the desired of	frice
Com	#4 Electronic Submission For OXY USA mitted to AFMSS for proce	INCORPORATED essing by PRISCIL	sent to the C LA PEREZ on	Carlsbad 01/09/2020 (20PP0791SE)	,
			1120027		NOOK .	
Solid Well Gas Well Other Contact LESUE REEVES Part Contact LESUE REEVES Part Contact LESUE REEVES Part Contact LESUE REEVES Part Contact Contact LESUE REEVES Part Contact C						
Notice of Intent Acidize Deepen Production (Start/Kesume) Water Shut-Off						
onditions of approval, if any, are attached	table title to those rights in the	not warrant or subject lease		JM ENGINE	ER	Date 01/29/2020
itle 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a catements or representations as t	crime for any person to any matter within	knowingly and vits jurisdiction.	villfully to ma	ke to any department or a	gency of the United
-4			1			

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #497183 that would not fit on the form

Wells/Facilities, continued

Agreement NMNM43744

Lease NMNM43744

Well/Fac Name, Number API Number PLATINUM MDP1 34-3 FEDERAL GO-0012646559-00-X1

NMNM43744

NMNM43744

PLATINUM MDP1 34-3 FEDERAL GOAM 25#6558-00-X1

Location

Location
Sec 34 T23S R31E NENE 110FNL 793FEL
32.267887 N Lat, 103.759689 W Lon
Sec 34 T23S R31E NENE 110FNL 898FEL
32.267887 N Lat, 103.760025 W Lon

Revisions to Operator-Submitted EC Data for Sundry Notice #497183

Operator Submitted

Sundry Type:

APDCH

NOI

Lease:

NMNM80645

Agreement:

Operator:

OXY USA INC PO 4294 HOUSTON, TX 77210 Ph: 713-497-2492

Admin Contact:

LESLIE REEVES REGULATORY ADVISOR E-Mail: LESLIE REEVES@OXY.COM Cell: 281-733-0824 Ph: 713-497-2492

Tech Contact:

LESLIE REEVES REGULATORY ADVISOR E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824 Ph: 713-497-2492

Location:

State: County:

NM **EDDY**

Field/Pool:

COTTON DRAW; BONE SPRING

Well/Facility:

PLATINUM MDP1 34-3 FEDERAL COM 26H Sec 34 T23S R31E Mer NMP NENE 110FNL 793FEL

general to the

32.267886 N Lat, 103.759688 W Lon

BLM Revised (AFMSS)

APDCH

NOI

NMNM43744

OXY USA INCORPORATED 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521 Ph: 713.350.4816

LESLIE REEVES

REGULATORY ADVISOR E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824

Ph: 713-497-2492

LESLIE REEVES

REGULATORY ADVISOR E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824

Ph: 713-497-2492

MM EDDY

COTTON DRAW-BONE SPRING

PLATINUM MDP1 34-3 FEDERAL COM 26H Sec 34 T23S R31E NENE 110FNL 793FEL 32.267887 N Lat, 103.759689 W Lon PLATINUM MDP1 34-3 FEDERAL COM 25H Sec 34 T23S R31E NENE 110FNL 898FEL

32.267887 N Lat, 103.760025 W Lon

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: OXY USA Incorporated

LEASE NO.: NMNM043744

LOCATION: Section 34, T.23 S., R.31 E., NMPM

COUNTY: Eddy County, New Mexico

WELL NAME & NO.: Platinum MDP1 34-3 Federal Com 25H

SURFACE HOLE FOOTAGE: 110'/N & 898'/W **BOTTOM HOLE FOOTAGE** 20'/S & 1260'/W

WELL NAME & NO.: | Platinum MDP1 34-3 Federal Com 26H

SURFACE HOLE FOOTAGE: | 110'/N & 793'/E **BOTTOM HOLE FOOTAGE** | 20'/S & 440'/E

COA

ALL PREVIOUS COAS STILL APPLY.

A. SPECIAL REQUIREMENT (S)

BOP Break Testing Variance (Note: For 5M BOP or less)

- While in transfer between wells, the BOPE shall be secured by the hydraulic carrier or cradle.
- Any well control event while drilling require notification to the BLM Petroleum Engineer prior to the commencement of any BOP Break Testing operations.
- A full BOP test is required prior to drilling the first deep intermediate hole section. If any subsequent hole interval is deeper than the first, a full BOP test will be required.

Oxy USA Inc. - Platinum MDP1 34-3 Fed Com 25H & 26H

This is a bulk sundry request for x2 wells in Eddy County, Section 34 T23S R31E. The wells related to this sundry request are:

API#	Weil	Name:
3001546558	Platinum MDP1 34	-3 Fed Com 25H
3001546559	Platinum MDP1 34	-3 Fed Com 26H

1. Casing Program

Oxy requests to increase the 2nd intermediate hole size to 8.75in and will plan to run x4 casing strings. The updated casing table is shown below:

5									Buoyant	Buoyant
Hole Size		Interval	Csg. Size		· Call	Conn.	SF.	on n	Body SF	Joint SF
(in),	From (ft)	To (ft)	(in)	(lbs)	Grade	Conn.	. Collaps e	SF Burst	Tension	Tension
17.5	0	722	13.375	54.5	J-55	BTC	1.125	1.2	1.4	1.4
12.25	0	4411	9.625	40	L-80	BTC	1.125	1.2	1.4	1.4
8.75	0	4000	7.625	26.4	L-80 HC	SF	1.125	1.2	1.4	1.4
6.73	4000	8277	7.625	26.4	L-80 HC	FJ	1.125	1.2	1.4	1.4
6.75	0	19221	5.5	20	P-110	DQX	1.125	1.2	1.4	1.4
							SE.	Values will r	neet or Evee	ed

All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.h

2. Cementing Program

Oxy requests to change the production cement job, increasing the cement volume to account for the larger intermediate hole size. The tables below highlight the changes.

			,	3 1		
Casing String	#\Sks	Wt: (lb/gal)	Yld (ft3/sack)	H20 (gal/sk)	500# Comp. Strength (hours)	Slurry Description
Surface (Lead)	N/A	N/A	N/A	N/À,	N/A	N/A
Surface (Tail)	766	14.8	1.33	6.365	5:26	Class C Cement, Accelerator
Intermediate (Lead)	937	12.9	1.88	10. J'30	14:22	Pozzolan Cement, Retarder
Intermediate (Tail)	155	14.8	1.33	6.370	12:45	Class C Cement, Accelerator
Intermediate II 1st Stage (Lead)	N/A	N/A	N/A	N/A	N/A	N/A
Intermediate II 1st Stage (Tail)	89	13.2	1.65	8.640	11:54	Class H Cement, Retarder, Dispersant, Salt
Intermediate II 2nd Sta	ge (Tail Slurry) to be pumpe	ed as Bradenh	ead Squeeze	from surface,	down the Intermediate annulus
Intermediate II 2nd Stage (Lead)	N/A	N/A	N/A	N/A	N/A	ìvà
Intermediate II 2nd Stage (Tail)	442	12.9	1.92	10.410	23:10	Class C Cement, Accelerator
Production (Lead)	N/A	N/A	N/A	N/A	N/A	N/A
Production (Tail)	839	13.2	1.38	6.686	3:49	Class H Cement, Retarder, Dispersant, Salt

^{*}Oxy requests the option to set casing shallower yet still below the salts if losses or hole conditions require this. Cement volumes may be adjusted if casing is set shallower.

^{*}Oxy requests the option to run DQX or SF-Torq connections for the 5.5" 20# P-110 production liner

Oxy USA Inc. - Platinum MDP1 34-3 Fed Com 25H & 26H

	2011									
Casing String	Top (ft)	Bottom:(ft)	% Excess.							
Surface (Lead)	N/A	N/A	N/A							
Surface (Tail)	0 \	722	100%							
Intermediate (Lead)	0	3911	50%							
Intermediate (Tail)	3911	4411	20%							
Intermediate II 1st Stage (Lead)	N/A	N/A	N/A							
Intermediate II 1st Stage (Tail)	6900	8277	5%							
Intermediate II 2nd Stage (Lead)	N/A	N/A	N/A							
Intermediate II 2nd Stage (Tail)	0	6900	25%							
Production (Lead)	N/A	N/A	N/A							
Production (Tail)	7777	19221	20%							

Oxy requests a variance to cement the 9.625" and/or 7.625" intermediate casing strings offline in accordance to the approved variance, EC Tran 461365.

The summarized operational sequence will be as follows:

- 1. Run casing as per normal operations. While running casing, conduct negative pressure test and confirm integrity of the float equipment (float collar and shoe).
- 2. Land casing.
- 3. Fill pipe with kill weight fluid, and confirm well is static.
 - a. If well is not static notify BLM and kill well.
 - b. Once well is static notify BLM with intent to proceed with nipple down and offline cementing.
- 4. Set and pressure test annular packoff.
- 5. After confirmation of both annular barriers and internal barriers, nipple down BOP and install cap flange. If any barrier fails to test, the BOP stack will not be nippled down until after the cement job is completed.
- 6. Skid rig to next well on pad.
- 7. Confirm well is static before removing cap flange.
- 8. If well is not static notify BLM and kill well prior to cementing or nippling up for further remediation.
- 9. Install offline cement tool.
- 10. Rig up cement equipment.
 - a. Notify BLM prior to cement job.
- 11. Perform cement job.
- 12. Confirm well is static and floats are holding after cement job.
- 13. Remove cement equipment, offline cement tools and install night cap with pressure gauge for monitoring.

Oxy requests permission to adjust the CBL requirement after bradenhead cement jobs, on 7-5/8" intermediate casings, as per the agreement reached in the OXY/BLM meeting on September 5, 2019.

Four string wells:

- CBL is not required
- If the pumped volume of cement is less than permitted in the APD, BLM will be notified and a CBL may be run
- Echometer will be used after bradenhead cement job to determine TOC before pumping top-out cement

Oxy USA Inc. – Platinum MDP1 34-3 Fed Com 25H & 26H

3. Pressure Control Equipment

Updated Pressure control equipment table to reflect 8.75in Open Hole Size:

BOP installed and	Marian Allendar	••Min.				
tested before drilling. which hole?	Size:	Negetine WP	Nic		lested in:	
		3M	Annular	v	70% of working pressure	
12.25" Hole	13-5/8"		Blind Ram	1	•	
12.23 11016	13-3/6	3M	Pipe Ram		250 : / 2000 :	
		31/1	Double Ram	✓	250 psi / 3000 psi	
1			Other*			
	13-5/8"	3M	Annular	1	70% of working pressure	
8.75" Hole		3M	Blind Rain	✓		
6.73 Hole			Pipe Ram		250 :/2000 :	
			Double Ram ✓		250 psi / 3000 psi	
			Other*			
		3M	Annular	✓	70% of working pressure	
6.75" Hole	13-5/8"		Blind Ram	√		
0.75 11016	13-3/8	3M	Pipe Ram		1	
			Double Ram	V	250 psi / 3000 psi	
			Other*			

^{*}Specify if additional ram is utilized.

Oxy will utilize a 5M annular with a 10M BOPE stack. The BOP/BOPE will be tested by an independent service company to 250 psi low and the high pressure indicated above per Onshore Order 2 requirements. The System may be upgraded to a higher pressure but still tested to the working pressure listed in the table above. If the system is upgraded all the components installed will be functional and tested.

4. BOP Break Testing Request

Oxy requests permission to adjust the BOP break testing requirements as per the agreement reached in the OXY/BLM meeting on September 5, 2019.

BOP break test under the following conditions:

- After a full BOP test is conducted
- When skidding to drill an intermediate section where ICP is set into the third Bone Spring or shallower.
- When skidding to drill a production section that does not penetrate into the third Bone Spring or deeper. If the kill line is broken prior to skid, two tests will be performed.
 - 1) Wellhead flange, co-flex hose, kill line connections and upper pipe rams
 - 2) Wellhead flange, HCR valve, check valve, upper pipe rams

If the kill line is not broken prior to skid, only one test will be performed.

1) Wellhead flange, co-flex hose, check valve, upper pipe rams

Well	Hole Size	Casing String	Shoe Depth (TVD)	Formation	Intermediate or Production	Mud Weight	Shell Test
Platinum MDP1 34-3 Fed Com 25H	12.25"	40# - 9.625"	4,465	Lamar	Intermediate	9.8-10.0	Yes
Platinum MDP1 34-3 Fed Com 26H	12.25"	40# - 9.625"	4,465	Lamar	Intermediate	9.8-10.0	Yes

Oxy USA Inc. – Platinum MDP1 34-3 Fed Com 25H & 26H

		SIZIMO ZIMUM	WIII 1111111 .	13191ca Con	1 2311 00 2011		
Platinum MDP1 34-3	8.75"	26.4# - 7.625"	8,167	Brushy	Intermediate	9.0-9.4	Yes
Fed Com 25H							
Platinum MDP1 34-3	8.75"	26.4# - 7.625"	8,258	Brushy	Intermediate	9.0-9.4	Yes
Fed Com 26H					ļ. 1		
Platinum MDP1 34-3	6.75"	20# - 5.5"	8,954	Bone Spring	Production	9.0-9.6	Yes
Fed Com 26H							
Platinum MDP1 34-3	6.75"	20# - 5.5"	8,864	Bone Spring	Production	9.0-9.6	Yes
Fed Com 25H			'				

Total estimated cuttings volume: 1524.5 bbls.