

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APU) for such proposals

FORM APPROVED
OMB NO. 1004-0135
EXPIRES: NOVEMBER 30, 2000

SUBMIT IN TRIPLICATE

1a. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other _____

2. Name of Operator
DEVON ENERGY PRODUCTION COMPANY, LP

3. Address and Telephone No.
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198

4. Location of Well (Report location clearly and in accordance with Federal requirements)*
990 FNL 2310 FEL B 34 17S 27E

5. Lease Serial No.

NMNM0557370

6. If Indian, Allottee or Tribe Name

7. Unit or CA Agreement Name and No.

8. Well Name and No.

Eagle 34 B Federal 52

9. API Well No.

30-015-33274

10. Field and Pool, or Exploratory

Red Lake; San Andres

12. County or Parish 13. State

Eddy

NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

2/23/06 MIRU PU. POOH with rods and pump. ND WH and NU BOP. POOH with tubing. RIH with RBP and packer and set RBP at 2816'. Pull up one joint and set packer. Tested RBP to 4000 psi - held good. Release packer.

2/24/06 POOH with tubing and packer. Dumped 2 sacks of sand on top of RBP. Perforated formation from 1866-2205'; 40 holes. RIH with packer and set at 1772'. Acidize San Andres with 3000 gallons of 15% HCl.

2/25/06 Released packer and POOH with packer and tubing.

2/27/06 Frac formation with 220,000 gallons of Aqua Frac 1000, 135,500# Brown sand 20/40, and 24,500# of Siberprop 16/30.

2/28/06 RIH with tubing, pump and rods. Hung well on production.

3/01/06 RDMO PU.

ACCEPTED FOR RECORD

JUN 22 2006

ALEXIS C. SWOBODA
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Signed Norvella Adams Name Norvella Adams Title Sr. Staff Engineering Technician Date 6/15/2006

(This space for Federal or State Office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: