

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	30-015-20029
5. Indicate Type of Lease	FEDERAL <del>STATE</del>
6. <del>XXXXXXXXXXXX</del>	
FEDERAL LEASE NO.	NMLC028731B
7. Lease Name or Unit Agreement Name	
DODD FEDERAL UNIT	
8. Well Number	17
9. OGRID Number	14049
10. Pool name or Wildcat	AGRBG JACKSON SR Q GRBG SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUG AND ABANDON AS FOLLOWS:

NOTIFY BLM 24 HRS BEFORE STARTING PLUGGING OPERATION.

1. POOH W/ PKR & TBG.
2. SHOOT 4 SQZ HOLES @ 895' (50' BELOW BASE SALT @ 845').
3. SET CIBP ON TBG @ 2400'. SPOT 10 SX CLASS "C" NEAT CMT ON CIBP. PULL UP TO 2100'. & CIRC WELL BORE FULL OF 9 PPG BRINE MIXED W/ 25 SX PER 100 BBLs SALT GEL (APPX 35 BBLs CSG VOLUME).
4. PULL TBG TO 745'. PUMP 45 SX CLASS "C" + 2% CACL2 TO END OF TBG (PLADING CMT IN/OUT OF CSG). TOOH W/ TBG, LOAD CSG. WOC A COUPLE HRS & TAG CMT W/ TBG.
5. SHOOT 4 SQZ HOLES @ 562' (50' BELOW 8 5/8" SHOE @ 512'). PUMP 175 SX CLASS "C" + 2% CACL2 DOWN 5 1/2" CSG & UP ANNULUS TO FILL WELL FROM 562' TO SURFACE W/ CMT.
6. CUT W/H & CSG OFF 3' BELOW FROUND LEVEL & REMOVE. WELD PLATE ONTO STUB. WELD 4" DRY HOLE MARKER ONTO PLATE @ 4' ABOVE GROUND LEVEL.
7. CUT OFF ANCHORS & RECLAIM LOCATION PER BLM SPECS.

\*\*\*BLM FORM 3160-5 SUBMITTED ON 6/13/06\*\*\*

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Diana J. Briggs TITLE PRODUCTION ANALYST DATE 6/13/06

Type or print name DIANA J. BRIGGS E-mail address PRODUCTION@MARBOB.COM Telephone No. (505) 748-3303

For State Use Only

APPROVED BY: \_\_\_\_\_ TITLE NMOCD DATE \_\_\_\_\_

Conditions of Approval (if any):

Accepted for record