

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

5
Form C-103
Revised June 10, 2003

WELL API NO. 220-015-06192	
Indicate Type of Lease STATE ☒ FEE ☐	
State Oil & Gas Lease No. BL-635	
7. Lease Name or Unit Agreement Name Leonard	
8. Well Number #1	
9. OGRID Number	
10. Pool name or Wildcat	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) LR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other Salt Dome Storage

2. Name of Operator
Lace Hill BSF

3. Address of Operator
158 Deer Creek Drive Alamo, Texas 76008

4. Well Location
Unit Letter L : 2069 feet from the South line and 1193 feet from the west line
Section 22 Township 12S Range 29E NMPM County Eddy

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Run cement bond log. If void exists in cement perforate casing + squeeze cement to fill void. If needed circulate cement from plug to surface. Let set and dr. 11 out. Perform Mit casing test (300 psi for 30 minutes) If passes then do open hole cavern test. (Nitrogen test not to exceed 300 psi.) for 4 hours

CBL 6/26/03 7:00 AM

Other ASAP after C.B.L

* Notify NMOLD to witness Repair + Test Actions taken on well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John B. Smith TITLE Terminal Operator DATE 6/25/03

Type or print name John B. Smith E-mail address: Telephone No. (505) 677-2331
(This space for State use)

APPROVED BY Mike Stuffle TITLE Environ. Eng. Spec. DATE 6/26/2003
Conditions of approval, if any: