Form 3160-5 (April 2004)

OCD-ARTESIA

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OM B No. 100 Expires: Marci	4-0137

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5.	Lease Serial No.
	LC-057798
6.	If Indian, Allottee or Tribe Name

7	IfIlm	it or C	A /A oros	ment	Name	and/or	Nic

SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil Well	Gas Well	1526	2728293037	8. Well Name and Na
2. Name of Operator Fairway Resources Operating, LLC				9. API Well No.
3a. Address 538 Silicon Drive, Suite 101, So	outhlake, TX 76092	3b. Phone No. (include 817-416-1946		30-015-20104 57 0. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R, M., or Survey Description) Unit Letter P, 990 feet from the south line and 990' from the east line Section 35-T17S-R27E Red Lake QN GB, SA 11. County or Parish, State Eddy County, NM				/11. County or Parish, State
12. CHECK AF	PPROPRIATE BOX(ES) TO	INDICATE NATUR		EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction ✓ Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal	Well Integrity Other

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
 - 1. RIH WITH CIBP DN @ 1600' AND SET
 - 2. PUMP 50' CMT PLUG ON TOP OF CIBP
 - 3. TAG CEMENT
 - 4. CIRCULATE MUD
 - 5. SPOT 50' CMT PLUG @ 700'

6. TAG PLUG

- 7. SPOT 56 CMT PLUG @ SURFACE 60′
- 8. INSTALL DRY HOLE MARKER AND CLEAN LOCATION

Work will commence when pulling unit available.


Accepted for record

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Title Office M	le Office Manager					
Date	07/18/2006					
PETRO	LEUM ENGINEER	_e JUL	26	2008		
rrant or lease Office						
	Date AL OR STATE Fille Tant or	AL OR STATE OFFICE USE PETROLEUM ENGINEER Date Trant or	Date 07/18/2006 AL OR STATE OFFICE USE PETROLEUM ENGINEER JUL Trant or	Date 07/18/2006 AL OR STATE OFFICE USE PATROLEUM ENGINEER JUL 2 6		

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Fairway Resources Operating, LLC South Red Lake II Unit #41



July 17, 2006