Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## BUKEAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5.	Lease Serial No.
	I CNINE OCCUPA

SUNDRY NOTICES AND	LCNM-062573				
Do not use this form for proposa	6. If Indian, Allottee or Tribe Name				
abandoned well. Use Form 3160 -	3 (APD) for such proposals.				
SUBMIT IN TRIPLICATE- Other i	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well	BIG EDDY UNIT				
Öil Well	8. Well Name and No.				
2. Name of Operator BASS ENTERPRISES PRODUCTIO	BIG EDDY UNIT # 84				
3a Address	3b. Phone No. (include area code)	9. API Well No. 30-015-23968			
P.O. BOX 2760 MIDLAND, TX 79702	432-683-2277 RECEIVED	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R, M, or Survey Description of Well (Footage, Sec., T., R, M, or Survey Description)	tion)	GOLDEN LANE (WOLFCAMP)			
1980' FNL 1980' FEL UL G, SEC 18, T21S, R29E	JUL <b>2 6 2006</b>	11. County or Parish, State			
	aco-na leok	EDDY COUNTY, NEW MEXICO			
12. CHECK APPROPRIATE BOX(ES	) TO INDICATE NATURE OF NOTICE, F	EPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION				
Acidize	Deepen Production (St	art/Resume) Water Shut-Off			
Notice of Intent Alter Casing	Fracture Treat Reclamation	Well Integrity			
Subsequent Report Casing Repair	New Construction Recomplete	Other			
Final Abandonment Notice Change Plans	Plug and Abandon ☐ Temporarily A ☐ Plug Back ☐ Water Disposal	<del></del>			
13. Describe Proposed or Completed Operation (clearly state al					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)					
SEE ATTACHMENT  Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is competed.  Accepted for record - NMOCD					
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)					
Cinki Lood	Title Production	, Clerk			
Signature Cindi Goodman	Date 7/11/04				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by (ORIG. SGD.) ALEXIS C. S	<del></del>	ENGINES JUL 2 4 2000			
Conditions of approval, if any, are attached. Approval of this certify that the applicant holds legal or equitable title to those which would entitle the applicant to conduct operations there	rights in the subject lease Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

## BASS ENTERPRISES PRODUCTION CO.

Lease: BIG EDDY UNIT #84

Project: P & A – CEMENTING REPORT

API # 30-015-23968

07-22-05 - SPOT 35 SXS @ 9905'-9416' & TAG 07-22-05 - SPOT 35 SXS @ 7600'-7171' & TAG

06-27-06 - PULL 3408' OF 5 1/2" CASING

06-28-06 - SPOT 45 SXS @ 3463'-3433' & TAG

06-29-06 - SPOT 40 SXS @ 3431'-3396'& TAG

06-29-06 - SPOT 25 SXS @ 3396'-3296'

06-29-06 - SPOT 55 SXS @ 3063'-2972' & TAG

06-29-06 - SPOT 30 SXS @ 2972'-2850'

06<sup>1</sup>29-06 - SPOT 60 SXS @ 819'-576' & TAG

06-30-06 - SPOT 25 SXS @ 60' TO SURFACE

Well Pha a 4/30/06 INSTALL DRY HOLE MARKER CIRCULATE 10# MUD

Darrell Carter W/ Blm Witnessed tag & suface plug.