Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Lease Serial No.

222627282930W

NM027994D

abandoned t	vell. Use Form 3160-3 (AP	D) for such proposa	RECEIVED IA	6 If Indian,	, Allottee or Tribe Name
SUBMIT IN T	RIPLICATE - Other instr	uctions on reverse	e Side 🕠	7. If Unit or	r CA/Agreement, Name and/or No
Type of Well			5/ 5/ CL 3/ 1/ 0/10	SW-	766
1. Type of Well Other Strand Other				8. Well Nar	
2. Name of Operator					AL MM COM #1
MARBOB ENERGY CORPORATION				9. API Well	
3a. Address 3b. Phone No. (include area code)				30-01	5-20856
PO BOX 227, ARTESIA, NM 88211-0227 (505) 748-3303				Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			_	BAD; MORROW, SOUTH	
			11. County o	r Parish, State	
1000 ENT 1000 ENT CEC 12 T22C D26E UNITE					
1980 FNL 1980 FWL, SEC. 13-T23S-R26E, UNIT F				EDDY	CO., NM
12. CHECK A	PPROPRIATE BOX(ES) TO	O INDICATE NATU	RE OF NOTICE, R	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat	Production (Star	Í	Water Shut-Off Well Integrity
Subsequent Report		New Construction	Recomplete	•	Other
Circl Abandanment Notice	· _	Plug and Abandon	Temporarily Ab	pandon	<u>- </u>
Final Abandonment Notice	Convert to Injection	Plug Back	■ Water Disposal		
Attach the Bond under which following completion of the in testing has been completed. For determined that the site is ready	ectionally or recomplete horizontal the work will be performed or provolved operations. If the operation inal Abandonment Notices shall be for final inspection.)	ly, give subsurface location wide the Bond No. on file tresults in a multiple com	ons and measured and true with BLM/BIA. Requi pletion or recompletion	red subsequent red subsequent r	s of all pertinent markers and zon reports shall be filed within 30 da l. a Form 3160-4 shall be filed or
NOTIFY BLM 24 F	RS BEFORE STARTING				
3. SPOT 100' F 4. SPOT 100' F 5. SPOT 100' F 6. SPOT 100' F 7. SPOT 100' F 8. SPOT PLUG F	E & PKR. 2 @ 11560' (PERF 116 2 LUG @ 8800' (TOP OF 2 LUG @ 5650' (9 5/8' 2 LUG @ 5440' (7" LIN 2 LUG @ 2000' (TOP OF 2 LUG @ 420' (13 3/8' 2 ROM 60' TO SURFACE. 3 L HEAD & INSTALL DE	F WOLFCAMP @ 87 ' SHOE @ 5600') NER TOP @ 5389' F DELAWARE @ 19 ' SHOE @ 367').	745').). '), WOC, TAG. 983').	ON TOP O	F CIBP.

14. I hereby certify that the foregoing is to	rue and correct			
Name (Printed/Typed)				
DIANA J. CANNON N		PRODUCTION ANALYST		
Signature	Da Da	august 22, 2003		
X	THIS SPACE FOR FEDERAL C	OR STATE OFFICE USE	Committee May 1997	
Approved by	and for fe	Title	Date	
Conditions of approval, if any, are attack certify that the applicant holds legal of which would entitle the applicant to condu	Approval of this notice does not warrant of equitable title to those rights in the subject lease of operations thereon.	Office		