Form 3160

FORM APPROVED OMB No. 1004-0135

Expires March 31, 2007

Do not use this form for proposals to drill or re entargan				NM-0486		
Do not use this form for proposals to drill or re enteren abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well				Big Eddy Unit		
Oil Well Gas Well X Other P&A				8. Well Name and No.		
2. Name of Operator				Big Eddy Unit #109Y		
Yates Petroleum Corporation				9. API Well No.		
3a. Address 3b. Phone No. (include area code)				30-015-25234		
105 S. 4th Str., Artesia, NM 88210 505-748-1471 4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)				10. Field and Pool, Fenton Delaw		
4. Location of Well (Footage, Geo., F., N., W., ON Survey Description)				11. County or Parish, State		
980'FSL & 1930'FEL of Section 21-T21S-R28E (Unit O, SWSE)				Eddy County, New Mexico		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE						
TYPE OF SUBMISSION			F ACTION			
	Acidize	Deepen	Production (S	Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
$\mathbf{X}_{\mathbf{A}}$	Casing Repair	New Construction	Recomplete		Other	
Subsequent Report	Change Plans X	Plug and Abandon	Temporarily .	Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	Water Disposal		
13. Describe Proposed of Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.						
testing has been completed. Final Abandonme determined that the site is ready for final inspection. 11/20/06 Pumped 60 bbls brine sx cement plug. 11/26/06 Spotted 50 sx cement 11/27/06 Tagged at 3138'. Circle Perforated at 975'. Plant 127/06 Tagged at 375'.	e down tubing. Parted 7 joir t at 3501'. WOC. No tag. culated plugging mud. Spo umped 40 sx cement plug.	nts below tubing a Re-spot 50 sx at t tted 30 sx cement WOC.	anchor. NO 3501'. WOO t at 2584'. V	TE: Received C. VOC. Tagged	approval to spot a 50	
11/28/06 Tagged at 877'. Circulated plugging mud. Perforated at 150'. Pumped 60 sx cement circulating to surface. 11/30/06 Cut off wellhead. Installed dry hole marker. WELL IS PLUGGED AND ABANDONED. FINAL REPORT.						
Approved as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed. Please notify Jim Krogman (505-365-8340) 3 days prior to BLM inspection, so we have the opportunity to meet with the inspector on location to confirm all reclamation requirements before receiving the notice of written order.						
14. I hereby certify that the foregoing is true a			3		TES BARYAK	
Name (Printed/Typed) Tina Huerta		Title Regulat	tory Complia	PETR ance Superviso	OLEUM ENGINEER or	
Signature (nerta	Date Decemb	ber 4, 2006			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Title		Date			
Conditions of approval, if any, are attached certify that the applicant holds legal or equit which would entitle the applicant to conduct or	ant or					
Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitious or fraudulent stater			willbully to make	to any department o	or agency of the United	