Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, 1914 88240 District II 30-005-63552 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, 1311 38216 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 E-92 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Quicksilver BCC State Com DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) FEB - 8 7001 1. Type of Well: Oil Well Gas Well G Other P& 2. Name of Operator 9. OGRID Number Yates Petroleum Corporation 025575 3. Address of Operator 10. Pool name or Wildcat 105 S. 4th Street, Artesia, NM 88210 Comanche Spring; Pre-Permian 4. Well Location Unit Letter 1980 feet from the North line and 660 feet from the West line 26 Township Section 10S Range **NMPM** Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3724'GR Pit or Below-grade Tank Application or Closure \_\_\_\_\_Depth to Groundwater \_\_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_\_ Distance from nearest surface water Pit Liner Thickness: Below-Grade Tank: Volume mil bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON 🛛 П **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1/31/07 - Set a 4-1/2" CIBP at 6002' with 35' cement on top. Circulated plugging mud. Perforated at 4512'. Spotted 25 sx cement at 4557'. 2/1/07 - Tagged at 4217'. Perforated at 2208'. Spotted 25 sx cement at 2247'. Displaced down casing to 1869'. WOC. Tagged at 1919'. Perforated at 655'. Spotted 55 sx cement. WOC. 2/2/07 - Tagged at 463'. Perforated at 60' and pumped 35 sx cement. Circulated to surface. Cut off wellhead. Installed dry hole marker. WELL IS PLUGGED AND ABANDONED. FINAL REPORT. Plugging of the well bore. Liability under bond is retained until surface restoration. environmental remediation and final inspection is completed. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines \_\_\_\_, a general permit \_\_\_\_\_ or an (attached) alternative OCD-approved plan \_\_\_\_\_. SIGNATURE ( TITLE Regulatory Compliance Supervisor DATE February 6, 2007 Tina Huerta Type or print name \_\_\_\_ E-mail address: tinah@ypcnm.com Telephone No. \_\_505-748-1471 Gerry Guye DATE FEB 9 2007 For State Use Only **Deputy Field Inspector** APPROVED BY: TITLE District II - Artesia Conditions of Approval (if any)