

Form 3160-5
(August 1998)Month - Year
MAR - 8 2007
OCD - ARTESIA, NMUNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

OCD-ARTESIA

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.
NM 18038 88954
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No.
NEL Federal #19
9. API Well No.
30-015-27327
10. Field and Pool, or Exploratory Area
East Loving, Delaware
11. County or Parish, State
Eddy, New Mexico

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other
2. Name of Operator
Pogo Producing Company
- 3a. Address 79702
P.O. Box 10340, Midland, TX 432-617-0208
- 3b. Phone No. (include area code)
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980 FNL & 1650 FEL
Sec 9, T-23-S, R-28-E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION


TYPE OF ACTION

☒ Notice of Intent☒ Subsequent Report☒ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. Move in Frac Tank to Circ. into.
2. Tag & Cap C.I.B.P. w/ 15 sx cement @ 3,638'.
3. PUH, spot 40 sx Plug @ 2,625-2,273', Salt & Delaware Tag.
4. Spot a 35 sx Plug 615' to 515' Tag.
5. 25 sx Plug @ Surface w/ Dry Hole Marker.

Approved by [Signature]
Title [Blank]
Date [Blank]



ORAL APPROVAL 3/1/07

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Howard Boatright

Title Agent

Signature

Date

02/27/07

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Pogo Producing Company

NEL Federal #9

