Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised June 10, 2003 WELL API NO.	
1625 N. French Dr., Language 88240 District II	625 N. French Dr., Harris 18240		WELL API NO. 30-015-33165	
1301 W. Grand Ave., 144 88210	d Ave., OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III			STATE S FEE	
1000 Rio Brazos Rd. Sec, N 9/410 Santa Fe, NM 87505		7505	5. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SACK TO A			Grandi	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM (-101) FOR SUCK PROPOSALS.)				
A AMON A TOTAL A		Aeg.	3. Well Number	
1 0 0 1 1		וווורס וווורס	2	
Oil Well Gas Well Other 2. Name of Operator OCD - ARTESIA, NIM OCD - ARTESIA, NIM		RITESIA, Non	9. OGRID Number	
Devon Energy Production Company, LP			5137	
3. Address of Operator			10. Pool name or Wildcat	
20 North Broadway Oklahoma City, Oklahoma 73102-8260 (405)552-4615		52-4615	Undesignated Esperanza; Delaware	
4. Well Location				
Unit LetterD_ :_660feet from the _North line and _660feet from the _Westline				
Section 22 Township 22S Range 27E NMPM Eddy County, NM				
Section 22 Township 22S Range 27E NMPM Eddy County, NM 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3103'				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEN ON MEMBER WORK	. 2007	112232770111		
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND ☐				
PULL OR ALTER CASING MULTIPLE CASING TEST AND			ABANDONMENT	
	COMPLETION	CEMENT JOB		
			_	
OTHER: MIT TEST & CHART FOR TA				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
02/27/07:				
	,			
MIRU pressure trck. Tie onto csg, ld w/pckr fluid; pressured up to 500# for 30 minutes w/chart recorder. No loss of pressure. R/D trck.				
Gerry Guye notified 02/26/07, no witness.				
NO CIBP				
	100 CZ 1	~ 1		
(See attached chart)	Temporary Abandone	ed StatusApproved		
(See attached chart) Temporary Abandoned StatusApproved Until 2-27-10				
	until 2-01	70		
I hereby certify that the information at	pove is true and complete to the be	est of my knowledge a	and belief.	
	4	. 00.75		
SIGNATURE ## / / / /	/ TITLE: Sr. S	taff Engineering Tech	nician DATE_03/07/2007	
Type or print name Stephanie A. Ysa	saga E-mail address: Stepha	nie Vsasaga@dvn cor	n Telephone No. 405-552-7802	
(This space for State use)	L-man address. Stepha	ino. i sasagawavii.coi	1 Ciephone No. 403-332-7802	
Gerry Guye MAD Q 2007				
APPPROVED BY	TITLE	Deputy Field Ins	WIAR 6 / 1111/	
Conditions of approval, if any: District # - Artesia				

