

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well



Oil Well



Gas Well



Other

2. Name of Operator

NEW MEXICO INSTITUTE OF MINING & TECHNOLOGY

3a. Address

601 D.Cox, SNL MS 0778, Box 5800, Albuquerque, NM 87185-0778

3b. Phone No. (include area code)

505-284-3871

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL 760 FWL U/L H SEC 24 T15S R29E

5. Lease Serial No.

LC069280-C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SULIMAR QUEEN UNIT

8. Well Name and No.

SULIMAR QUEEN UNIT TR 3 # 3

9. API Well No.

30-005-60066

10. Field and Pool, or Exploratory Area

SULIMAR QUEEN

11. County or Parish, State

CHAVES COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION



Notice of Intent



Subsequent Report



Final Abandonment Notice

TYPE OF ACTION



Acidize



Alter Casing



Casing Repair



Change Plans



Convert to Injection



Deepen



Fracture Treat



New Construction



Plug and Abandon



Plug Back



Production (Start/Resume)



Reclamation



Recomplete



Temporarily Abandon



Water Disposal



Water Shut-Off



Well Integrity



Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

SEE ATTACHMENT

Accepted for record
NMOCD

APPROVED AS TO PLUGGING OF THIS
WELL BORE. LIABILITY UNDER BOND
IS RETAINED UNTIL SURFACE RESTORATION
IS COMPLETED

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

JACK B. Tillman

Title

SNL Field Representative

Signature

Jack B. Tillman

Date

03/16/07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ DAVID R. GLASS

PETROLEUM ENGINEER

Date

MAR 20 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

NEW MEXICO INSTITUTE OF MINING & TECHNOLOGY

Lease: SULIMAR QUEEN UNIT TR 3 # 3

Project: P & A - CEMENTING REPORT

API # 30-005-60066

04-11-06 - SPOT 25 SXS @ 1890'-1608' TAGGED

04-11-06 - PERFORATE @ 1330'-TEST TO 600# - SPOT 40 SXS @ 1383'-1016' - TAGGED

04-12-06 - PULL 470' OF 5 1/2" CASING

04-12-06 - SPOT 60 SXS @ 535'-323' & TAG

04-12-06 - PERFORATE @ 250'-SQUEEZE 128 SXS @ 250' TO 6' TAGGED

04-13-06 - SPOT 2 SXS @ 6' TO SURFACE

INSTALL DRY HOLE MARKER

CIRCULATE 10# MUD