

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE
(Other instruction on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

NM-06814

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

RECEIVED

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Marbob Energy Corporation

AUG 11 '89

8. FARM OR LEASE NAME

Southern Union Federal

3. ADDRESS OF OPERATOR

P.O. Drawer 217, Artesia, New Mexico 88211-0217

9. WELL NO.

3

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirement. See also space 17 below.)
At surface

O. C. D.
ARTESIA, OFFICE

10. FIELD AND POOL, OR WILDCAT

No. Hackberry-Yates SR

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 30-T19S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether of, ft, gr, etc.)

3439' GR

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

RELL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We plugged & abandoned well as follows:

5/30/89 Sptd 25 sx plug @ TD, did not tag; sptd 50 sx plug, tagged @ 1350'; ran tbg to 525'; circ cmt to surface. Will notify you when location is cleaned and ready for inspection.

RECEIVED

Post ID-2
8-4-89
P&A

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Clerk

DATE

8/1/89

(This space for Federal or State office use)

APPROVED BY

FOR

CHIEF, MINERAL RESOURCES

DATE

8-10-89

CONDITIONS OF APPROVAL, IF ANY

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.


*See Instructions on Reverse Side

12 Southern Fed #3

Drilled 6/18/81

Plugged: 5/30/89

Run tbg. to 525'
circ to surface



50 SX plug @ 1350' tagged

25 SX plug

4 1/2" 10.50" 400 SX
2520'