

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 88410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised June 10, 2003

RECEIVED SEP 11 2003  
OCD - ARTESIA  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30 005 63301

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

26827

7. Lease Name or Unit Agreement Name

Willow Springs "16" State

8. Well Number

1

9. OGRID Number

149441

10. Pool name or Wildcat

Pecos Slope Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Reliance Energy, Inc.

3. Address of Operator

6 Desta Drive, Suite 5500, Midland, TX 79705

4. Well Location

Unit Letter N : 660 feet from the south line and 1980 feet from the west line

Section 16 Township 4S Range 25E NMPM County Chaves

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3864' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐ OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Set CIBP @ 3688' w/ 35' cmt.

Spot 30 sx @ 2000' - 1900' - TAG

→ 25 sx plug @ 1673' Perf. @ 874' Place 100' of ont inside & outside of cs. 874' - 974' - TAG

Spot 35 sx @ 60' surface

Perf cs. @ 60' Place 100' of ont. inside & outside of cs. 0' - 60' - woc 24 hrs - TAG

Salt gel mud consisting of 10#  
Brine W/25# of gel per bbl  
must be placed between each plug

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Clepper

TITLE Regulatory Analyst

DATE 9-11-2003

Type or print name Laura Clepper

E-mail address: lclepper@reimid.com Telephone No. 432 683-4816

(This space for State use)

APPROVED BY [Signature]

TITLE Field Rep ID

APPROVED SEP 16 2003

Conditions of approval, if any: