Form 3160-5 (February 2005)

Hole Marker.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS			N.M.	N.M. 564-26	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, All	ottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or Ca	VAgreement, Name and/or No	
1 Type of Well Oil Well X Gas Well Other		.1111 2 4 2007		8. Well Name and No. AL SOOT FEDERAL	
2. Name of Operator	OCD-ARTESIA		#2	EDEKAL	
SOUTHWEST ROYALTIES, INC.			9. API Well No).	
3a. Address		none No. (include area code)	130 013 221		
6 Desta Drive, Suite 2100, Midland, TX 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		1		Pool, or Exploratory Area	
660' FSL = 1980'FE	- '	T185, R29,		•	
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE	NATURE OF NOTICE	E, REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize Alter Casing		Production (Start/Resume)	Water Shut-Off	
Subsequent Report	Casing Repair		Reclamation Recomplete	Well Integrity Other	
Final Abandonment Notice	Change Plans X Convert to Injection		Cemporarily Abandon Water Disposal		
13. Describe Proposed or Completed Operation (clear If the proposal is to deepen directionally or recompact that the Bond under which the work will be perfollowing completion of the involved operations, testing has been completed. Final Abandonment determined that the final site is ready for final inspe	plete horizontally, give subsurface rformed or provide the Bond No If the operation results in a multi Notices shall be filed only after a	e locations and measured and b. on file with BLM/BIA. R ple completion or recomplet	I true vertical depths of all equired subsequent report ion in a new interval, a Fo	I pertinent markers and zones. s shall be filed within 30 days orm 3160-4 shall be filed once	
6-19-07 M.I.R.U. Basic Energy Ser	vice P & A Rig #1273.	Rig up Wireline &	go in hole w/3 1	./2" DumpBailer	
& tag T.O.C. @9,448'. Dum					
6-20-07 T.I.H. w/tbg. Circulate hw/tbg. Weld on 5 1/2" P.N. Remove		sure test @500# 30	minute. Csg. tes	st good. P.O.O.H.	
6-21-07 Cut 5 1/2" csg. @6,650'. hole S.D.F.N. 6-22-07 Tag T.O.C. Pull tbg. to 3,068' with 8 5/8" spot 40 sx. cmt. Calculate T.O.C.	06,531'. Pull tbg. to shoe plug. Spot 50 sx.	4,994'. Spot 40 s cmt. W.O.C. & Ta	x. cmt. Calculate g @2,932'. Pull t	T.O.C. @4,839'.	

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Gerry Guye, Deputy Field Inspectory RANDALL MINEAR NMOCD-District II ARTESIA Signature Date 7-3-07 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Tıtle Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon

6-25-07 Tag T.O.C.@337'. Pull tbg. to 100'. Spot 30 sx. cmt. to surface. Cut off well head & install Dry

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department. States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.