

**Bratcher, Mike, EMNRD**

---

**From:** Ray [rtaylor@hec-enviro.com]  
**Sent:** Monday, July 23, 2007 9:25 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** FW: COG Operating Reindeer Federal #1, API # 30-015-33746  
**Attachments:** COG Reindeer Fed #1 Final Pit Closure.pdf

-----Original Message-----

**From:** Ray [mailto:rtaylor@hec-enviro.com]  
**Sent:** Monday, July 23, 2007 10:16 AM  
**To:** 'rmcneill@hec-enviro.com'  
**Subject:** COG Operating Reindeer Federal #1, API # 30-015-33746

Raymond P. Taylor  
Highlander Environmental Corp.  
432-682-4559 Office  
432-425-6913 Cell

COG - Reindeer Federal #1

Cleared to close by Mike Bratcher on 7/11/2007, As per Mike Bratcher 3.0' of material was removed from the Southeast corner and blended with fresh top soil berm, the material was spread evenly on the bottom of the reserve pit. Mud was placed in a lined trench and covered with 3.0' of soil.

---

This inbound email has been scanned by the MessageLabs Email Security System.

---

7/27/2007