

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
OCD-ARTESIA

## SUNDRY NOTICES AND REPORTS ON WELLS

**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.**

FORM APPROVED  
OMB No. 1004-0137  
Expires. March 31, 2007

5 Lease Serial No. NM-25336

6. If Indian, Allottee or Tribe Name

7 If Unit or CA/Agreement, Name and/or No.

8. Well Name and No

Ranch Hand Federal #1

9. API Well No.

30-015-30691

10. Field and Pool, or Exploratory Area

Wildcat (Wolfcamp)

11. County or Parish, State

Eddy County, NM

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well Oil Well Gas Well Other

X

2. Name of Operator Nadel and Gussman Permian, LLC

AUG 07 2007

OCD-ARTESIA

3a. Address 601 N. Marienfeld, Suite 508  
Midland, TX 7970013b. Phone No. (include area code)  
432-682-4429

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter N: 660 feet from the South line and 1800 feet from the West line of Section 23,  
Township 20S, Range 21E

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other: Re-Entry & Production Casing Running & Cementing	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon		
	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

7/26/06 MIRU. Weld 11" 5M Flange and Extension on to 9-5/8" casing. NU &amp; test BOPs.

7/27/06 RIH and drill out cement plugs down to 2181'.

7/28/06 to 7/30/06 Drillout cement plugs down to 6300'. Start running 5-1/2" casing.

7/31/06 Finish running 5-1/2" 17# N80 LTC casing to 6157'. Circulate well, then pump 20 bbls chemical wash, 425 sx CemCrete blend lead (10.5 ppg, 2.04 CuFt/sk) and 685 sx TXI lightweight tail (13.0 ppg, 1.41 CuFt/sk). Displaced w/ 143 bbls FW, bumped plug w/ 1700 psi, floats held. ND BOP, set slips, NU tubing head and release rig.

Note: Casing in well prior to MIRU consisted of:

9-5/8" 36# casing set at 1400' in 12-1/4" hole and cemented to surface

ACCEPTED FOR RECORD

AUG 5 2007

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed) Terry West

Title Engineer

Signature

Date 6/20/2007

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Ar2rave~

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

Accepted for record - NMOC

8/8/07