Form 3160-5 February 2005)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-AKTESIA

FORM APROVED OMB NO. 1004-0137 EXPIRES: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE - Other instructions on page 2

	5. Lease Serial No.
	NM-NM84B
	6. If Indian, Allottee or Tribe Name
	7. Unit or CA Agreement Name and No.
2007	
	8 Well Name and No.
TESIA	Arco 20 Federal Com 2
	9. API Well No.
area code)	30-015-30599
	10. Field and Pool, or Exploratory Area
	Brushy/Cherry Canyon; Delaware
	11 County or Parich State

 Type of Well Oil Well ✓ Gas Well Other 2. Name of Operator **DEVON ENERGY PRODUCTION COMPANY, LP** 3a, Address 3b. Phone No. (include a 405-552-4615 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1320' FSL 2323' FWL 20 T21S R26E L. County or Parish, State NM Eddv 12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Production (Start/Resume) Acidize Deepen ☐ Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing ✓ Subsequent Report Casing Repair **New Construction** Recomplete Other ☑ Plug and Abandon Change Plans Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) MIRU on 8/24/07. Drill out cement and CIBP at 3090'. Drill out cement and CIBP at 3250'. 2. TIH to 9450' & circulate hole w/10 ppg mud. 3. Spot 40 Sx cement from 8264' to 8455'. Spot 30 Sx cement from 6321' to 6500'. 5. Spot 25 Sx cement from 4451' to 4600'. 6. Set 7" CIBP at 3730'. Dump 6 Sx (35') cement on top. (Brushy Canyon Perfs from 3780' - 3886') 7. Set 7" CIBP at 3090'. Dump 6 Sx (35') cement on top. (Brushy Canyon Perfs from 3140' - 3180') 8. Spot 60 Sx cement at 2400'. Tagged TOC at 2040'. (9-5/8" shoe at 2121'). 9. Spot 60 Sx cement at 650'. Tagged TOC at 370'. (13-3/8" shoe at 451'). 10. Perforated 7" casing at 150'. Circulated 60 Sx cement in/out to surface. 11. Cut wellhead off and set dry hole marker. Plugged & Abandoned - 10/2/07. **Accepted** for recura **NMOCD** 4. I hereby certify that the foregoing is true and correct Title **Engineering Technician** Name: Ronnie Slack Date Signature 10/2/2007 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by/S/ DAVID R. GLASS OCT 0 9 2007 **PETROLEUM ENGINEER** SPECIFICATION FUNCTION OF THE MELL SOME. LIMBLITY UNDER SOMD Conditions of approval, if any are attached. Approval of this SURFACE RESTORATION notice does not warrant or certify that the applicant holds legal or

equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon. Office

**MCOMPLETED** 

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

