N.M. On Come. DIV-Dist

DEC 14 2007

UNITED STATES TO STATE OF THE INTERIOR NEW 38210 BUREAU OF LAND MANAGEMENT

Form 3160-5 (April 2004)

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 OCD-AK I COLA

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					NM-58803	
					6. If Indian, Allottee or Tribe Name	
				U. II IIIGIZ	o. Il fidial, Alloce of Free Parit	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well				4		
✓ Oil Well Gas Well Other				8 Well N	8. Well Name and No.	
					Cobra Federal #2	
2. Name of Operator Armstrong Energy Corporation				9. API W		
			nclude area code) 30-005-63735			
P.O. Box 1973, Roswell, NM 88202 575-625-2			10. Field and Pool, or Exploratory Area		and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R, M, or Survey Description)				Coma	nche Draw	
1710' FSL & 950' FWL, Sec. 19-T11S-R27E				11. Count	11. County or Parish, State	
				Chave	Chaves, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	starv Resume)	Well Integrity	
]	Casing Repair	New Construction			Other	
Subsequent Report	Casing Repair  New Construction  Recomplete  Temporarily Abandon  Temporarily Abandon					
Final Abandonment Notice Convert to Injection Plug Back Water Disposal						
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.						
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  11-26-07 Set C.I.B.P. at 6130' and dumped 35' cement on top of plug. 11-27-07 Perforate 5178-82' and 5168-74', 2 jspf, 22 holes. 11-28-07 Acidize with 3000 gals 15% NEFE acid and ballsealers. Avg. pressure 3150 psi at 3 BPM. Max. 3530 psi, did not ball off. ISIP 2844 psi, 15 min. 2723 psi. Flowed down, made 5 swab runs, swabbed down to S.N., no show. 11-29-07 S.I.T.P. 100 psi, acid gas. Swabbed 3 BLW, no show. Prep to reperf. 12-3-07 G.I.H. with Stimgun and reperforate 5178-82' and 5168-74',6 jspf, 62 holes. T.I.H. with packer. Swabbed 17 BLW, no show. 12-4-07 Acidize with 5000 gals. 20% Fercheck acid with 4000 lbs. rock salt in four stages. Average 3647 psi at 5 BPM. Max. 6366 psi. Isip 2883 psi, 15 min. 2726 psi. Flowed and swabbed 63 BLW, no show. P.O.H. with packer. T.I.H. with bit and drilled out C.I.B.P. 12-5-07 S.I.T.P. 220 psi, acid gas, Swabbed 8 BLW, no show. P.O.H. with packer. T.I.H. with bit and drilled out C.I.B.P. 12-6-07 Finish running rods, space out, load tubing, started pumping.  Returned Fusselman zone to production, no gas, oil or water from test perfs.						
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)						
Bruce A. Stubbs		Title	Title Vice President - Operations			
Signature Date			Date 12/10/2007			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
	****		T	<b>_</b>		
Approved by			Title		PORTED FOR DECORD	
Conditions of approval, if any, are attached Approval of this notice does not warran				<del>-   AC</del> C	FLIED LOK KENOKO	
certify that the applicant holds legal or equitable title to those rights in the subject leas			Office	.  - r		
which would entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to states any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						

(Instructions on page 2)

GARY GOURLEY
PETROLEUM ENGINEER