## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.



FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMLC029418A

l	
6.	If Indian, Allottee or Tribe Name

		-, 101 0u011 p.					
SUBMIT IN TRIF	7. If Unit or CA/Agreement, Name and/or No. NMNM71030A						
1. Type of Well	8. Well Name and No.						
Oil Well Gas Well 💆 Oth	SKELLY UNIT 38						
Name of Operator     FOREST OIL CORPORATION	Contact: E-Mail: cabush@fo	,		9. API Well No 30-015-10770-00-S1			
3a. Address 707 17TH STREET SUITE 36 DENVER, CO 80202	3b. Phone No. Ph: 303-812 Fx: 303-864			10. Field and Pool, or Exploratory GRAYBURG			
4. Location of Well (Footage, Sec., T.	, R., M , or Survey Description			11. County or Parish, a	nd State		
Sec 23 T17S R31E NWNE 56	OFNL 1980FEL	0 8 2008		EDDY COUNTY, NM			
		_	-ARTESIA				
12. CHECK APPR	OPRIATE BOX(ES) TO	INDICATE	NATURE OF N	NOTICE, RE	PORT, OR OTHER	DATA	
TYPE OF SUBMISSION	<del>,</del>	TYPE OF ACTION					
Nation of Internal	Acidize	П Deep	en	Product	ion (Start/Resume)	□ Water Shu	ut-Off
Notice of Intent	Alter Casing	Fracture Treat		☐ Reclama	ation	□ Well Integ	
Subsequent Report	Casing Repair	☐ New Construction ·		Recomplete		Other	
Final Abandonment Notice	Change Plans	□ Plug and Abandon		_	arily Abandon	ш	
	Convert to Injection	_		□ Water D			
testing has been completed. Final Aldetermined that the site is ready for form of the corrected Proposed Procedur  1. MIRU 2. Dump 35' cmt (25 sxs) on to see the control of the corrected Proposed Procedur  3. Pull Tubing & packer at 323 and the corrected Proposed Procedur  4. RIH w/CIBP, set @ 3,300'. and the corrected Proposed Procedur  5. RIH w/tubing, tag cement plud  6. Circ hole w/mud laden fluid  7. Spot 100' cement plug 1650 and the corrected Proposed Procedure  8. Circ hole w/mud laden fluid  9. Spot 100' cement plug 576-	e to Plug and Abandon V op of CIBP @ 3660' 5' as required. Cap w/25 sx cmt ug 0-1750'. WOC, tag cement p	tiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once all requirements, including reclamation, have been completed, and the operator has a ACCEPTED FOR RECORD  Gerry Guye, Deputy Field Inspector  NMOCD-District II SEESTTACHED FOR  CONDITIONS OF APPROVAL					
	# Electronic Submission For FOREST ( mitted to AFMSS for proc	DIL CORPORA	TION, sent to the RT SIMMONS on	e Carlsbad 02/06/2008 (0	8KMS0903SE)		
Name (Printed/Typed) CINDY BU	Title SR. RE	GULATORY	TECH				
Signature (Electronic S		Date 02/05/2	008			_	
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By JAMES A AMOS	TitleSPET			Date 02	/06/20		
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conditions.	Office Carlsba	d					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S C. Section 1212, make it a	a crime for any p	erson knowingly an	nd willfully to i	nake to any department of	or agency of the U	United

## Additional data for EC transaction #58450 that would not fit on the form

32. Additional remarks, continued

10.Circ hole w/mud laden fluid
11. Perf casing w/4 way squeeze perf at 60'

Before

Skelly Unit #38 300 1510770 11" Hole 1 676 850 50-(Circ)
FEAT 630 50-(Circ) TOS 475' BOS 1700' 77/8" Hole 3313 -3618 Perfs @ 3660 Parts 3842-3907' TD 3935 5½" Cs. Circ. through Several Remedial jobs through the life of the well.

the 13th of the well. Remedial jobs through Cinc, through Several 150 ..3/5 2868 CT 9778 25 5x balanced pluy 1098-5485 241.9 35' Cmt (W/Bailor) or 2778 0 24,29 3775- 2155 7/8" 19:15 ·95 3 1650- 1750 Bos 1700 \$5.0601 Jal Balaned Phy Base of Sell To 574-725 Tag 1.8 55-I .8/58 60' - Suc Kace,

11" Hole

ノチナタ

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.