

OCD-ARTESIA

Form 3160-5
(August 2007)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FEB 21 2008

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM LCO6896D

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MARKS + GARNER PRODUCTION

3a. Address

P.O. BOX 1089

3b. Phone No. (include area code)

575-393-9358

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SWNW 8 12S 29E NMP Eddy NM

7. If Unit of CA/Agreement, Name and/or No.

NM NM 70800X

8. Well Name and No.

Cave Pool 41

9. API Well No.

30-015-02926

10. Field and Pool or Exploratory Area

GRAYBLAD JACKSON

11. Country or Parish, State

Eddy, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

- ☐
- Notice of Intent
-
- ☐
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☐
- Acidize
- ☐
- Deepen
- ☐
- Production (Start/Resume)
- ☐
- Water Shut-Off
-
- ☐
- Alter Casing
- ☐
- Fracture Treat
- ☐
- Reclamation
- ☐
- Well Integrity
-
- ☐
- Casing Repair
- ☐
- New Construction
- ☒
- Recomplete
- ☐
- Other
-
- ☐
- Change Plans
- ☐
- Plug and Abandon
- ☐
- Temporarily Abandon
-
- ☐
- Convert to Injection
- ☐
- Plug Back
- ☐
- Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

RIG UP PULLING UNIT, RIG UP B.O.P.
RIG UP REVERSE UNIT + PITS, BACK UP BIT, COLLARS
+ TUBING, DRILL OUT PLUG, PULL TBG, LAY DOWN COLLARS
RUN PACTER TEST CASINGS, SWAB TEST ZONE. TRACT
AND RUN PRODUCTION STRING SEE PUMPING UNIT,
HOOK UP ELECTRICAL, SEE BATTERIES + FLOW LINES,
PUT ON PRODUCTION

ACCEPTED FOR RECORD

FEB 15 2008

LES BABYAK
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

QUINTON WELBORN

Title MANAGER

Signature

Quinton W. Welborn

Date

2-8-08

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)