District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 May 27, 2004

Submit to appropriate District Office

☐ AMENDED REPORT

Form C-101

APPL	ICATI	ON FO	R PERMIT	TO DI	RILL, RE-	ENTER, D	EEPEN	, PLUGBA	CK, OR A	DD A ZONE
Operator Name and Address Devon Energy Production Company, L. P. 20 North Broadway						OGRID Number 6137			mber 7	
Oklahoma City, OK 73102-8260							.30	API Numl	36197	
Property Code Property N									Well No.	
300635 Cotton Draw				w Unit 111 10 Proposed Pool 2				111		
13370	tlen	Ma	Proposed Pool 1	hu.	pnyon			Пор	JSEQ 1 001 2	,
			,		- //	Location				
UL or lot no. Section Township Range		Lot Idn Feet from		om the North/	South line	Feet from the	East/West line	e County		
С	36	24S	31E				orth	1980	West	Eddy
Г <u></u>					tion If Different From Surface					
UL or lot no	Section	Township	Range	Lot	ldn Feet fr	om the North/	South line	Feet from the	East/West line	e County
	l			Ad	Iditional We	ell Informati	on			
11 Work	Type Code N		¹² Well Type Co O		13 Cabi	e/Rotary R		14 Lease Type Code 15 Ground Level Elevation S 3503' GL		
	Iultiple No		¹⁷ Proposed Dep 9100'	th	h 18 Formation Delaware; Brushy Canyon			19 Contractor		²⁰ Spud Date 3/15/08
Depth to Groundwater 100' Distance from nearest fresh				sh water well				e water 1000' or		
Pit: Liner	Synthetic		mils thick Clay	☐ Pit V	olume:bb	k D	rilling Meth	od:		
Close	ed-Loop Sys	tem 🛚						🛛 Brine 🕅 Die	esel/Oil-based	Gas/Air G
			21	Propos	sed Casing a	and Cement	Progran	n		
Hole Size Casing Size Casing weight/foot Setting Depth Sacks of Cement Estim				Estimated TOC						
17 ½	,,,	1	3 3/8"	48# H-40 ST&C		0' - 8	50',	, 700 sx	Cl C	Surface
			8 5/8"			0'-40		1800 sx		Surface
7 7/8" 5 1/2"		5 1/2"	15.5# /17# J55		$\frac{0'-9}{}$	0' - 9100'		Cl H	500' Inside	
Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary. 1. Cement Program: a. 20" Conductor Cement w/ ready-mix to surface.						ed new productive zone.				
	b. 13	3/8"	Surface		Cmt to st 2% CaCl2	urf w/500 + ¼#/sx (sx Poz CF + 20	(35:65 Po 0 sx Cl C	oz, Cl C w/2% Ca	, 6% gel) w/ Cl2 + ¼#sx CF.
	c. 8 5/8" Intermediate Cmt to surf w/1600 sx Poz 35:65 Poz, Cl C, 6% gel, 15% salt w/ $\frac{1}{4}$ /sx CF + 200 sx Cl C w/2% CaCl2, + 1/4 $\frac{1}{4}$ /sx CF.									
	d. 5 ½" Production Cmt 1 st stg w/525 sx Silica Lite H w/3% salt, 0.6% FL ¼#/sx CF. Cmt 2 nd stg w/225 sx Poz 35:65 H 6% gel w/¼#/sx CF + 400 sx H w/ 4% gel 5% salt ¼#/sx CF.									
			on given above is to			OIL CONSERVATION DIVISION				
best of my knowledge and belief. I further certify that the drilling pit will be constructed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan .				Approved by: Jens W. Seers						
Printed name:	Judy A. Bai	mett (20	57)un us	Title: Whates II agree too				
Title: Regulat	ory Analyst		0	,		Approval Date: 3/17/118 Expiration Date: 3/17/10				
E-mail Addres	E-mail Address: Judith.Barnett@dvn.com							· · · · · · · · · · · · · · · · · · ·		
Date:2/14/08 Phone:405-228-8690				Conditions of Annoyal Attached						

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 DISTRICT II 1301 W. Grand Avenue, Artesia, NM 88210

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-102 Revised October 12, 2005

Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, New Mexico 87505

■ AMENDED REPORT

			METT TO	CATION	AND ACREA	GE DEDICATI	ON PLAT		
API	inn	Pool Code				Pool Name	· · · · · · · · · · · · · · · · · · ·		
30-01	9197		<u>37() </u>		atton Dra	W; BRUSH	CANYON		
Property (Code		Property Name COTTON DRAW UNIT					Well Number	
OGRID No				Operator Nam		· · · · · · · · · · · · · · · · · · ·		111	
6137		DEVON	J ENFR	-	ION COMPANY	I P		Elevation 3503'	
0137		l	DEVOI	LIVEIN	Surface Loca				
UL or lot No.	Section	l m	h n	Lot Idn	Feet from the	North/South line	P-4 8 Al-	East/West line	
· ·	36	Township 24 S	Range 31 F	Lot lan	660	NORTH	Feet from the	WEST	County
С	36	24 3		<u>i </u>				WESI	EDDY
			Bottom			erent From Sur	face		
UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
D-1:4-1 4	- 1 7-1-1 -	- 1-401 6-	<u> </u>	0-1- 0-					
Dedicated Acres	s Joint o	r innii Co	nsolidation	Code Ur	der No.				
L									
NO ALLO	WABLE W					JNTIL ALL INTER APPROVED BY		EN CONSOLIDA	ATED
	1	//	/ 		<u> </u>		OPERATO	R CERTIFICAT	TION
	<i>\ </i>	. 09	}	t	ļ		11	rlify that the inform	
	-	_	•		 		contained heren	n is true and comp knowledge and beliet	lete to
-	<u>1980' ک</u> ر) 1		LOCATION 210'45.40"		this organization	n either owns a worl ased mineral interesi	ing
	1			Long - W	/103'44'01.12"		location pursua	the proposed bottom in it to a contract with ral or working intere	an owner
	i	,	•	[, E.;	429472.956 426872.698		a voluntary poo	ling agreement or a ing order heretofore	
	· — — 4	-	- <i>بہ</i> ےر ۔۔۔ بہ ے	1 <u> </u>	0-83) + -		the division.	1.	
	i		•		i		11 /2	(S)	->-
	i				i		Signature	7/2an	Date
	1				l				
	- 1				1		Judy A. Barne		2/14/08
	- 1				l		Printed Nam	Regulatory Ana	llyst
	!				!		SURVEYO	R CERTIFICAT	ION
	1				1		I hereby sortes	that the well locat	ion shows
	i			1) [on this plat w	as plotted from field	i notes of
	,			ŀ	i		11	made by me or d that the same is	-
	i				i		3 3	e best of my belie	
	ĺ				i		FEBR	UARY_7_2008	,
	i				1		Date Survey	A 1. 10	
l	+			 -	+-		Signature Professional	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	۱ ۱
	Į.				ļ				.))
	!				!		11		
[]	!				1		1		
	 				ł,		W.S		
	 				1		Certificate N	o. Gary L. Jones	7977
				<u></u>				asin surveyS	

Proposed Mud Circulation System:

Depth	Mud Wt	Visc	Fluid Loss	Type system
0'-850'	8.8	34-36	NC	Fresh Water
850'-4000	10.0	28	NC	Brine Water
4000'- TD	8.8	32-36	10-20	Fresh Water

The BOP will consist of a 3M system double ram type 3000 psi WP preventor w/ bag type Hydril preventor 3000 psi. All BOP's and associated equipment will be tested to 1200 psi w/ rig pump before drilling out the 8 5/8" casing shoe (70% of 48#, H-40 casing). The estimated BHP is 2900 psi and the estimated BHT is 130.

There is no known presence of H2S in this area. All personnel will be familiar with all aspects of safe operation of equipment being used to drill this well.

This location is not an NSL.

See attached C-102

See attached nearby Gas Analysis.





Laboratory Services, Inc.

2609 West Marland Hobbs, New Mexico 88240

Telephone: (505) 397-3713

FOR:

Devon Energy

P.O. Box 250

Artesia, New Mexico 88211-0250

SAMPLE:

Sta. # 39033075

IDENTIFICATION Cotton Draw #90

Devon Energy

COMPANY: LEASE:

PLANT:

SAMPLE DATA: DATE SAMPLED

11/26/07 11/27/07

ANALYSIS DATE: PRESSURE - PSIA

54 61

GAS (XX) SAMPLED BY: LIQUID () Lemmons

SAMPLE TEMP. °F

ATMOS, TEMP. °F

ANALYSIS BY:

Vicki McDaniel

REMARKS:

H2S = 0

COMPONENT ANALYSIS

		MOL	
COMPONENT		PERCENT	GPM
District Confession	41,000	0.000	
Hydrogen Sulfide	(H2S)	0.000	
Nitrogen	(N2)	2.979	
Carbon Dioxide	(CO2)	0.089	
Methane	(C1)	69.307	
Ethane	(C2)	12.841	3.426
Propane	(C3)	8.616	2 369
I-Butane	(IC4)	1.070	0.349
N-Butane	(NC4)	2.606	0.820
I-Pentane	(IC5)	0.684	0.250
N-Pentane	(NC5)	0.735	0.266
Hexane Plus	(C6+)	1.073	0.466
		100.000	7.946
BTU/CU.FT DRY	/ 13'	72	MOLECULAR WT. 23.8041
AT 14.650 DRY	130	67	
AT 14.650 WET	13	44	
AT 14.73 DRY	13		
AT 14.73 WET	13:	-	
VI 14'12 MEI	13	J	•

SPECIFIC GRAVITY -CALCULATED

MEASURED

0.820

Office Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resource	es May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	N - The state of t
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
District IV	Saina Pc, INVI 67303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
	ATION FOR PERMIT" (FORM C-101) FOR SUCH	Cotton Draw Unit
PROPOSALS.)	Gas Well -Other -	8. Well Number
1. Typ e of Well: On Well 	Gus weit Guier ————————————————————————————————————	111
2. Name of Operator		9. OGRID Number
Devon Energy Production Company	y, LP	6137
3. Address of Operator		10. Pool name or Wildcat
20 North Broadway Oklahoma Cit	y, Oklahoma 73102-8260 (405)228-8699	Delaware; Brushy Canyon
4. Well Location		
1	eet from theNorth line and1980	feet from the West line
	aship 24S Range 31E NMPN	
	11. Elevation (Show whether DR, RKB, RT, C	rK, etc.)
Pit or Below-grade Tank Application ☐ or		South and the state of the stat
Pit typeDepth to Groundwa	terDistance from nearest fresh water well	
Pit Liner Thickness: mil	Below-Grade Tank: Volumeb	bls; Construction Material
12 Check A	ppropriate Box to Indicate Nature of N	otice Report or Other Data
12. Check 1	appropriate box to indicate reature of re	onec, report of Other Data
NOTICE OF IN	TENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		L WORK ALTERING CASING
	CHANGE PLANS COMMEN	_
TEMPORARILY ABANDON	i	CE DRILLING OPNS. P AND A
TEMPORARILY ABANDON	<u></u>	-
TEMPORARILY ABANDON DULL OR ALTER CASING	MULTIPLE COMPL CASING/C	CE DRILLING OPNS. P AND A
TEMPORARILY ABANDON DULL OR ALTER CASING DUHER: I	MULTIPLE COMPL CASING/CO	CE DRILLING OPNS.☐ P AND A ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OTHER: I 13. Describe proposed or complete proposed or complete proposed Dull Office Pro	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det	CE DRILLING OPNS. P AND A EMENT JOB ails, and give pertinent dates, including estimated date
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OTHER: I 13. Describe proposed or complete proposed or complete proposed Dull Office Pro	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det	CE DRILLING OPNS.☐ P AND A ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR AL	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion	CE DRILLING OPNS. P AND A EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion of starting any proposed we or recompletion. Devon Energy Production	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det	CE DRILLING OPNS. P AND A EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 1 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the propo	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD.
TEMPORARILY ABANDON DULL OR ALTER CASING DITER: 1 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly 20)	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion 1 L.P. requests to change the proposed of the p	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD.
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 1 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly 20 Calcium Chloride + 93.6% Fresh Warden Poul Calcium Chloride + 93.6% Fre	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack later	EMENT JOB A Cails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 1 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly 20 Calcium Chloride + 93.6% Fresh Wa Tail w/ 250 sacks Premium Plus C C	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion 1 L.P. requests to change the proposed of the p	EMENT JOB A Cails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc
TEMPORARILY ABANDON DULL OR ALTER CASING DESCRIPTION OF STATE OF THE PROPERTY OF THE PUBLIC OF THE P	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the pr	EMENT JOB P AND A Calls, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly A Calcium Chloride + 93.6% Fresh Wa Tail w/ 250 sacks Premium Plus C C 8 5/8" Intermediate Lead w/1025 sacks (35:65) Poz (Fly	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Soc	EMENT JOB A Cails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly A Calcium Chloride + 93.6% Fresh Wa Tail w/ 250 sacks Premium Plus C C 8 5/8" Intermediate Lead w/1025 sacks (35:65) Poz (Fly bwoc Bentonite + 107.8% Fresh Water Complete Section 107.8% Fresh Water Complete Section 107.8% Fresh Water Cash	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societer	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Complete Start	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 5% bwow Society sh):Premium Plus C Cement + 5% bwow Society	EMENT JOB P AND A Calls, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Water Tail w/ 250 sacks Premium Plus C Ctor S 5/8" Intermediate Lead w/1025 sacks (35:65) Poz (Fly bwoc Bentonite + 107.8% Fresh Water Tail w/300 sacks (60:40) Poz (Fly Abwoc Sodium Metasilicate + 4% bwoc Sodium Metasi	MULTIPLE COMPL CASING/COTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 2% bwoc Calcium Chloride + 0.125 lbs/sack atter lement + 5% bwow Society sh):Premium Plus C Cement + 5% bwow Society	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Water Tail w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Water Tail w/ 250 sacks (35:65) Poz (Fly bwoc Bentonite + 107.8% Fresh Water Tail w/300 sacks (60:40) Poz (Fly Action Charles) Production	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societ sch:Premium Plus C C	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% am Chloride + 0.125 lbs/sack Cello Flake + 0.4%
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Complete of the Start of the St	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the p	EMENT JOB Ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% am Chloride + 0.125 lbs/sack Cello Flake + 0.4% ium Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Complete Start	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societ sch:Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 3% bwow Societ Ash):Premium Plus C Ceme	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% am Chloride + 0.125 lbs/sack Cello Flake + 0.4% ium Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack 5% Fresh Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Water Tail w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Water Tail w/ 250 sacks (35:65) Poz (Fly Bwoc Bentonite + 107.8% Fresh Water Tail w/300 sacks (60:40) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (60:40) Poz (Fly Action Lead w/ 355 sacks (60:40)	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societ sh):Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 3% bwow Societ Ash):Premium Plus C Cement + 3% bwow Societ Ash):Premium Plus C Cement + 1% bwow Societ Ash):Premium Plus C Ceme	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% am Chloride + 0.125 lbs/sack Cello Flake + 0.4% ium Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack Fresh Water am Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed we or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Water Tail w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Water Tail w/ 250 sacks (35:65) Poz (Fly Bwoc Bentonite + 107.8% Fresh Water Tail w/300 sacks (60:40) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (60:40) Poz (Fly Action Lead w/ 355 sacks (60:40)	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societ sch:Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 3% bwow Societ Ash):Premium Plus C Ceme	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% am Chloride + 0.125 lbs/sack Cello Flake + 0.4% ium Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack Fresh Water am Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Watali w/ 250 sacks (35:65) Poz (Fly Action Chloride + 107.8% Fresh Watali w/300 sacks (60:40) Poz (Fly Action Chloride + 107.8% Fresh Watali w/300 sacks (60:40) Poz (Fly Action Chloride + 3 lbs/sackLCM-1 + 0.3 Tail w/785 sacks (60:40) Poz (Fly Action Chloride + 3 lbs/sackLCM-1 + 0.3 Tail w/785 sacks (60:40) Poz (Fly Action Chloride + 2 lbs/sack CelloFlake + 2 lbs/sac	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack atter ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societ sh):Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 3% bwow Societ Ash):Premium Plus C Cement + 1% bwow Societ Ash):Premium Plus C Ceme	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% om Chloride + 0.125 lbs/sack Cello Flake + 0.4% om Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack 5% Fresh Water om Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3 th Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 107.8% Fresh Watali w/ 300 sacks (35:65) Poz (Fly Action Chloride + 107.8% Fresh Watali w/ 300 sacks (60:40) Poz (Fly Action Chloride + 4% bwo Sodium Metasilicate + 4%	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the p	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% om Chloride + 0.125 lbs/sack Cello Flake + 0.4% om Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack 5% Fresh Water om Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3 th Water owledge and belief. I further certify that any pit or below-
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 107.8% Fresh Watali w/ 300 sacks (35:65) Poz (Fly Action Chloride + 107.8% Fresh Watali w/ 300 sacks (60:40) Poz (Fly Action Chloride + 4% bwo Sodium Metasilicate + 4%	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the p	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% om Chloride + 0.125 lbs/sack Cello Flake + 0.4% om Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack 5% Fresh Water om Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3 th Water
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 93.6% Fresh Watali w/ 250 sacks Premium Plus C Ctoron Chloride + 107.8% Fresh Watali w/ 300 sacks (35:65) Poz (Fly Action Chloride + 107.8% Fresh Watali w/ 300 sacks (60:40) Poz (Fly Action Chloride + 4% bwo Sodium Metasilicate + 4%	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the p	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% om Chloride + 0.125 lbs/sack Cello Flake + 0.4% om Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack 5% Fresh Water om Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3 th Water owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly & Calcium Chloride + 93.6% Fresh Wa Tail w/ 250 sacks Premium Plus C C8 5/8" Intermediate Lead w/1025 sacks (35:65) Poz (Fly & Boylow Bentonite + 107.8% Fresh Wa Tail w/300 sacks (60:40) Poz (Fly & Boylow Sodium Metasilicate + 4% bwo Sodium Metasilicate + 2 lbs/s Cello Flake + 3 lbs/sack LCM-1 + 0.3 Tail w/785 sacks (60:40) Poz (Fly Astronomy Metasilicate + 2 lbs/s I hereby certify that the information of grade tank has been/will be constructed or	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of the p	EMENT JOB ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion cementing program to the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc os/sack Cello Flake + 56.3% Fresh Water dium Chloride + 0.125 lbs/sack Cello Flake + 6% om Chloride + 0.125 lbs/sack Cello Flake + 0.4% om Chloride + 0.25% bwoc R-3 + 0.125 lbs/sack 5% Fresh Water om Chloride + 0.5% bwoc BA-10A + 0.1% bwoc R-3 th Water owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or completion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly & Calcium Chloride + 93.6% Fresh Wa Tail w/ 250 sacks Premium Plus C C8 5/8" Intermediate Lead w/1025 sacks (35:65) Poz (Fly & Boylow Bentonite + 107.8% Fresh Wa Tail w/300 sacks (60:40) Poz (Fly & Boylow Sodium Metasilicate + 4% bwo Sodium Metasilicate + 2 lbs/s Cello Flake + 3 lbs/sack LCM-1 + 0.3 Tail w/785 sacks (60:40) Poz (Fly Astronomy Metasilicate + 2 lbs/s I hereby certify that the information of grade tank has been/will be constructed or	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack ster ement + 2% bwoc Calcium Chloride + 0.125 lb Ash):Premium Plus C Cement + 5% bwow Societ sh):Premium Plus C Cement + 5% bwow Societ sh):Premium Plus C Cement + 5% bwow Societ Ash):Premium Plus C Cement + 3% bwow Societ Ash):Premium Plus C Cement + 1% bwow Societ Ash):Premium Plus C Cement +	DEEMENT JOB Description of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commenting commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc by sack Cello Flake + 6% Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc bwoc bwoc bwoc bwoc bwoc bwoc
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed wo or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly And Surface) Lead w/ 450 sacks Premium Plus C Complete or Calcium Chloride + 93.6% Fresh War Tail w/ 250 sacks Premium Plus C Complete or Castal w/ 1025 sacks (35:65) Poz (Fly Bown Bentonite + 107.8% Fresh War Tail w/ 300 sacks (60:40) Poz (Fly And Surface) Lead w/ 320 sacks (35:65) Poz (Fly And Surface) Lead w/ 320 sacks (35:65) Poz (Fly And Surface) Lead w/ 320 sacks (60:40) Poz (Fly And Surface) Lead w/ 320 sacks (60:40) Poz (Fly And Surface) Lead w/ 320 sacks (60:40) Poz (Fly And Surface) Lead w/ 320 sacks (60:40) Poz (Fly And Surface) Lead w/ 320 sacks (60:40) Poz (Fly And Surface) Lead w/ 320 sacks (60:40) Poz (Fly And Surface) Lead w/ 450 sacks (60:40) Poz (Fly And Surface) Lead w/ 450 sacks (60:40) Poz (Fly And Surface) Lead w/ 450 sacks (35:65) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:40) Poz (Fly And Surface) Lead w/ 1025 sacks (60:	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack ash):Premium Plus C Cement + 5% bwow Sociater ement + 2% bwoc Calcium Chloride + 0.125 lbs Ash):Premium Plus C Cement + 5% bwow Sociater sh):Premium Plus C Cement + 5% bwow Sociater Ash):Premium Plus C Cement + 3% bwow Sociater Ash):Premium Plus C Cement + 1% bwow Sociater	DEEMENT JOB Description of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commenting commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc bwoc bwoc bwoc bwoc bwoc bwoc
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed wo or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Water Tail w/ 250 sacks Premium Plus C Ctoron Chloride + 107.8% Fresh Water Tail w/ 1025 sacks (35:65) Poz (Fly bwoc Bentonite + 107.8% Fresh Water Tail w/ 1025 sacks (60:40) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (60:40) Poz (Fly Action Lead w/ 320 sacks (60	MULTIPLE COMPL CASING/O OTHER: leted operations. (Clearly state all pertinent det rk). SEE RULE 1103. For Multiple Completion L.P. requests to change the proposed of Ash):Premium Plus C Cement + 0.125 lbs/sack ash):Premium Plus C Cement + 5% bwow Sociater ement + 2% bwoc Calcium Chloride + 0.125 lbs Ash):Premium Plus C Cement + 5% bwow Sociater sh):Premium Plus C Cement + 5% bwow Sociater Ash):Premium Plus C Cement + 3% bwow Sociater Ash):Premium Plus C Cement + 1% bwow Sociater	DEEMENT JOB Description of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commenting commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc bwoc bwoc bwoc bwoc bwoc bwoc
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: I 13. Describe proposed or complete of starting any proposed wo or recompletion. Devon Energy Production 13 3/8" Surface Lead w/ 450 sacks (35:65) Poz (Fly Action Chloride + 93.6% Fresh Water Tail w/ 250 sacks Premium Plus C Ctoron Chloride + 107.8% Fresh Water Tail w/ 1025 sacks (35:65) Poz (Fly bwoc Bentonite + 107.8% Fresh Water Tail w/ 1025 sacks (60:40) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (35:65) Poz (Fly Action Lead w/ 320 sacks (60:40) Poz (Fly Action Lead w/ 320 sacks (60	MULTIPLE COMPL	DEEMENT JOB Description of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commenting commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 56.3% Fresh Water Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 56.3% Fresh Water Chloride + 0.125 lbs/sack Cello Flake + 6% Commentation of the APD. Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc by sack Cello Flake + 6% Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc by sack Cello Flake + 6% Cello Flake + 6% Cello Flake + 6% bwoc Bentonite + 2% bwoc bwoc bwoc bwoc bwoc bwoc bwoc bwoc

SECTION 36, TOWNSHIP 24 SOUTH, RANGE 31 EAST, N.M.P.M., NEW MEXICO. EDDY COUNTY,

OFF SET 3503 4

DEVON ENERGY PRODUCTION CO., L.P. COTTON DRAW UNIT #111 Elev. - 3503'

0

150' EAST □ OFF SET 3502.7'

Lat.-N 32*10'45.40" Long-W 103*44'01.12" (NAD-83)

-----_ LEASE ROAD

150' SOUTH OFF SET 3500.1'

Directions to Location:

FROM MILE MARKER 19 OF STATE HWY 128, GO EAST 0.3 MILES TO CO. RD. 786, ON CO. RD. 786 GO SOUTH FOR 4.6 MILES TO CO. RD. 791, ON CO. RD. 791 GO SOUTH BY SOUTHEAST FOR 3.1 MILES TO LEASE ROAD, ON LEASE ROAD GO EAST 1.9 MILES TO COTTON DRAW WELL IN SECTION 11, THENCE NORTH 0.7 MILES, THENCE WEST 0.3 MILES, THENCE NORTH 0.3 MILES, THENCE EAST 0.7 MILES, THENCE 0.8 MILES NORTH TO PROPOSED LOCATION.

BASIN SURVEYS P.O. BOX 1786 - HOBBS, NEW MEXICO

W.O. Number: 19065 J. M. SMALL Drawn By:

Sheet

Sheets

0

200

400 FEET

SCALE: 1" = 200

DEVON ENERGY PROD. CO., L.P.

COTTON DRAW UNIT #111 / WELL PAD TOPO

THE COTTON DRAW UNIT #111 LOCATED 660' FROM THE NORTH LINE AND 1980' FROM THE WEST LINE OF SECTION 36, TOWNSHIP 24 SOUTH, RANGE 31 EAST,

N.M.P.M., EDDY COUNTY, NEW MEXICO.


Survey Date: 02-07-2008

200

1

Date: 02-12-2008

Disk: 19065W




COTTON DRAW UNIT #111 Located at 660' FNL AND 1980' FWL Section 36, Township 24 South, Range 31 East, N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786 1120 N. West County Rd. Hobbs, New Mexico 88241 (505) 393-7316 - Office (505) 392-3074 - Fax basinsurveys.com

W.O. Number:	JMS 19065T
Survey Date:	02-07-2008
Scale: 1" = 2	000,
Date: 02-12-	-2008

DEVON ENERGY PROD. CO., L.P.



COTTON DRAW UNIT #111 Located at 660' FNL AND 1980' FWL Section 36, Township 24 South, Range 31 East, N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786 1120 N. West County Rd. Hobbs, New Mexico 88241 (505) 393-7316 - Office (505) 392-3074 - Fax basinsurveys.com

	W.O. Number: JMS 19065TR
	Survey Date: 02-07-2008
	Scale: 1" = 2 MILES
l	Date: 02-12-2008

DEVON ENERGY PROD. CO., L.P.