CHICK			A 01111 O 1 0-
District I	Energy, Minerals and Nat	ural Resources	May 27, 2004 LL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		V.	30-015-35987
1301 W. Grand Ave., Artesia, NM 88210	ÖÏL CONSERVATION		Indicate Type of Lease
District III	1220 South St. Fra	ncis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505	State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	S AND REPORTS ON WELLS	S 7.	Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL		UG BACK TO A	Č
DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	ION FOR PERMIT" (FORM C-101) F	<u> </u>	G J WEST COOP UNIT
1. Type of Well: Oil Well Gas	s Well Other MA	N Z O 7IIIIR	Well Number 180
2. Name of Operator	_	PARTESIA 9.	OGRID Number 229137
COG	Operating LEO		Pool name or Wildcat 97558
Texas Ave., Suite 1	300 Midland,	•	J; 7RVS-QN-GB-GLORIETA-YESO
4. Well Location			
Unit Letter O :	990' feet from the South	line and1650'	feet from the <u>East</u> line
Section 16	Township 17S	Range 29E	NMPM County EDDY
	. Elevation (Show whether DR		
Pit or Below-grade Tank Application or Clo	3560	GR	The state of the s
Pit type DRILLING Depth to Groundwa		from harmaton moll 1000' Di	istones from possess surface water 4000'
			stance from nearest surface water1000'
	w-Grade Tank: Volume	bbls; Construction Mat	
12. Check Appr	copriate Box to Indicate N	ature of Notice, Repo	ort or Other Data
NOTICE OF INTE	NTION TO:	SUBSEC	QUENT REPORT OF:
	UG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
<u> </u>	IANGE PLANS	COMMENCE DRILLING	
	JLTIPLE COMPL	CASING/CEMENT JOB	
		ON TO THE OFFICE AND THE OFFI	
		_	`
OTHER:			SKID RIG
13. Describe proposed or completed	operations. (Clearly state all p	ertinent details, and give	pertinent dates, including estimated date
 Describe proposed or completed of starting any proposed work). 	operations. (Clearly state all p SEE RULE 1103. For Multipl	ertinent details, and give	
13. Describe proposed or completed	operations. (Clearly state all p SEE RULE 1103. For Multipl	ertinent details, and give	pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work). or recompletion.	SEE RULE 1103. For Multipl	ertinent details, and give e Completions: Attach v	pertinent dates, including estimated date vellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well	SEE RULE 1103. For Multipl	ertinent details, and give e Completions: Attach v 5', regain partial retu	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @
13. Describe proposed or completed of starting any proposed work). or recompletion.	SEE RULE 1103. For Multipl 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck (ertinent details, and give e Completions: Attach v 5', regain partial retu	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3.	SEE RULE 1103. For Multipl 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck (ertinent details, and give e Completions: Attach v 5', regain partial retu	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this wel 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co	SEE RULE 1103. For Multipl I 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of ould not work shoe free.	ertinent details, and give e Completions: Attach v 5', regain partial retu csg @ 65'. Work free uid Started flowing o	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co. 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr. Gumm @ 9:00pr	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck could not work shoe free. Shoe. Push fish to 185'. Flan and received verbal plu	ertinent details, and give e Completions: Attach v 5', regain partial retu csg @ 65'. Work free uid Started flowing o gging orders. Pump	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this wel 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck could not work shoe free. Shoe. Push fish to 185'. Flan and received verbal plu	ertinent details, and give e Completions: Attach v 5', regain partial retu csg @ 65'. Work free uid Started flowing o gging orders. Pump	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Cog 3/11/08 Fishing Texas ptrn guide so Notified OCD Mr. Gumm @ 9:00pr down to lost circ @ 65' as per Mr. Cog 13. Shoe in hole. Title w/ 17 ½" bit. Cog 15. Shoe in hole. Title w/ 17	SEE RULE 1103. For Multiple 13-10-08. Lost circ @ 6/8" 48# J-55 csg. Stuck could not work shoe free. Shoe. Push fish to 185'. Firm and received verbal plu Gumm. No cement to surface.	ertinent details, and give e Completions: Attach v 5', regain partial retu csg @ 65'. Work free uid Started flowing o gging orders. Pump ace.	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co. 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr. Gumm @ 9:00pr	SEE RULE 1103. For Multiple 13-10-08. Lost circ @ 6/8" 48# J-55 csg. Stuck could not work shoe free. Shoe. Push fish to 185'. Firm and received verbal plu Gumm. No cement to surface.	ertinent details, and give e Completions: Attach v 5', regain partial retu csg @ 65'. Work free uid Started flowing o gging orders. Pump ace.	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this wel 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr C 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of which had not work shoe free. Shoe. Push fish to 185'. Flem and received verbal plugumm. No cement to surfact with C with C community C commun	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Completion of th	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of buld not work shoe free. Shoe. Push fish to 185'. Flan and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' lead to 1140' FSL & LOCATION: 1140' FSL &	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Completion of th	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this wel 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr C 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of buld not work shoe free. Shoe. Push fish to 185'. Flan and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' lead to 1140' FSL & LOCATION: 1140' FSL &	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Completion of th	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of buld not work shoe free. Shoe. Push fish to 185'. Flan and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' lead to 1140' FSL & LOCATION: 1140' FSL &	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Completion of th	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am.
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW program will remain the same as the	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Firm and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' I LOCATION: 1140' FSL & G J WEST COOP UNIT #1	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Completion of th	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface from @ 7:45am. Sting pad & drill the ned plat). Casing & cementing
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Firm and received verbal plurianm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' le LOCATION: 1140' FSL & G J WEST COOP UNIT #1	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Complete of the Comp	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am. Sting pad & drill the ned plat). Casing & cementing
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide so Notified OCD Mr. Gumm @ 9:00pr down to lost circ @ 65' as per Mr. Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm GJ WEST COOP UNIT #180Y. NEW program will remain the same as the I hereby certify that the information above grade tank has been/will be constructed or closed.	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Film and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' leads to Skid the rig 150' leads according to NMOCD guidelines is true and complete to the besaccording to NMOCD guidelines.	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Complete of the Comp	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am. Sting pad & drill the ned plat). Casing & cementing relief. I further certify that any pit or belowttached) alternative OCD-approved plan .
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide so Notified OCD Mr. Gumm @ 9:00pr down to lost circ @ 65' as per Mr. Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW program will remain the same as the I hereby certify that the information above	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Film and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' leads to Skid the rig 150' leads according to NMOCD guidelines is true and complete to the besaccording to NMOCD guidelines.	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Complete of the Comp	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am. Sting pad & drill the ned plat). Casing & cementing
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW program will remain the same as the I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Film and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' I LOCATION: 1140' FSL & G J WEST COOP UNIT #1 is true and complete to the besaccording to NMOCD guidelines	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Complete of the Comp	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface from management of the first proposed with the ned plat). Casing & cementing celief. I further certify that any pit or belowttached) alternative OCD-approved plan DATE 3-14-08
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW program will remain the same as the I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Film and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' I LOCATION: 1140' FSL & G J WEST COOP UNIT #1 is true and complete to the besaccording to NMOCD guidelines	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Complete of the Comp	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface for Gumm @ 7:45am. Sting pad & drill the ned plat). Casing & cementing relief. I further certify that any pit or belowttached) alternative OCD-approved plan .
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW program will remain the same as the I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name Kanicia Carrillo For State Use Only	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Firm and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx dission to skid the rig 150' I LOCATION: 1140' FSL & G J WEST COOP UNIT #1 is true and complete to the best according to NMOCD guidelines in TITLE	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Completion of th	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface from main main main main main main main mai
13. Describe proposed or completed of starting any proposed work). or recompletion. COG Operating LLC spud this well 9:15 p.m. 3/10/08. Ran 2 jts 13 3. Shoe in hole. TIH w/ 17 ½" bit. Co 3/11/08 Fishing Texas ptrn guide s Notified OCD Mr Gumm @ 9:00pr down to lost circ @ 65' as per Mr Co 3/12/08 Pump cmt plug #2 100sx COG Operating LLC received perm G J WEST COOP UNIT #180Y. NEW program will remain the same as the I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name Kanicia Carrillo For State Use Only	SEE RULE 1103. For Multiple 1 3-10-08. Lost circ @ 6 /8" 48# J-55 csg. Stuck of build not work shoe free. Shoe. Push fish to 185'. Film and received verbal plugumm. No cement to surface w/4% Cacl2. Circ 20sx ission to skid the rig 150' I LOCATION: 1140' FSL & G J WEST COOP UNIT #1 is true and complete to the besaccording to NMOCD guidelines	ertinent details, and give e Completions: Attach versions of the Completions of the Completions of the Completions of the Complete of the Comp	pertinent dates, including estimated date vellbore diagram of proposed completion rns. TD 17 ½" hole @ 331' @ e. TOH w/csg. Left TX PTRN utside of cellar and under rig. 100sx C cmt plug #1 from surface from main main main main main main main mai

DISTRICT I

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-102

DISTRICT II
1901 V. GRAND AVENUE, ARTERIA, NO BERLO

1000 Rio Brasos Ed., Artec, NM 87410

OIL CONSERVATION DIVISION 1220 SOUTH ST. FRANCIS DR. Santa Fe, New Mexico 87505 Revised October 12, 2006 Submit to Appropriate District Office State Lease ~ 4 Copies Fee Lease ~ 3 Capies

DISTRICT IV

DISTRICT III

WELL LOCATION AND ACREAGE DEDICATION PLAT

I AMENDED REPORT

LESS S. ST. PEARCH SE., BARTA PE, RE	67060		CI AMENDED REPORT		
API Number	Pool Code	Pool Code Pool Name			
30-015-	97558	GJ; 7 RVS-QN-GB-GLORIETA-YESO			
Property Code	P	roperty Name	Well Number		
302497	GJ WES	GJ WEST COOP UNIT			
OGRID No.	0	perator Name	Elevation		
229137	COG OF	PERATING, LLC	3560		

Surface Location

Section	Township	Range	Lot idn	Feet from the	North/South line	Feet from the	East/West line	County
16	17-S	29-E		1140	SOUTH	1650	EAST.	EDDY

Bottom Hole Location If Different From Surface

UL or lot No.	Section	Township	Renge	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
) 		
Dedicated Acres	Joint o	r Infili Co	nsolidation (ode Or	der No.				
40							_		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

<u></u>				
				OPERATOR CERTIFICATION I hereby certify that the information herein is true and complete to the best of my knowledge and belief, and that this organization alther owns a working interest or unleased mineral interest in the land including the proposed bottom hale location or has a right to drill this well at this location pursuant to a contract with an owner of such mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
				Synature Date
		,		Phyllis A. Edwards Printed Name Regulatory Analyst
				SURVEYOR CERTIFICATION
				shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.
				NOVEMBER 2007
,	GEODETIC COORDINATES NAD 27 NME	111-	1650'	Signature & Seal Ss Professional Surveyor
•	Y=665886.3 N X=579003.6 E	1140'		Morall / Entry 114/08
	LAT. = 32.830344* TN LONG. = 104.076134* W	+		Certificate No. GARY C. EIDSON 12841 RONALD J. EIDSON 3239