

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-61284 NA
1. Type of Well: Oil Well ☐ Gas Well ☒ Other		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Jack J. Grynberg, dba Grynberg Petroleum Company		6. State Oil & Gas Lease No. NA
3. Address of Operator 5299 DTC Boulevard, Suite 500 Greenwood Village, CO 80111-3321		7. Lease Name or Unit Agreement Name McDermett 30 Com
4. Well Location Unit Letter A : 990 feet from the N line and 660 feet from the E line Section 30 Township 6S Range 25E NMPM County Chaves		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3774 GR		9. OGRID Number A 30 6S 25E
Pit or Below-grade Tank Application ☐ or Closure ☐		10. Pool name or Wildcat Undesignated Abo
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Ground Tank: Volume _____ bbls, Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work).

SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10 3/4 casing @ 912', 7 5/8 casing @ 1871', 4 1/2 casing @ 3962'.

TOC on 10 3/4 is 818'. TOC on 4 1/2 is 3090'. Perforations are 3450 to 3699, 27 holes.

2 3/8 tubing @ 3390'.

Plugging Procedure:

1. MI-RU pulling unit.

2. Pull and lay down tubing.

3. Set CIBP @ # 3425. Drop 2x cement on top.

4. Shoot off 4 1/2" casing @ 3000'. Lay 50' cement plug from 2950-3000'.

5. Pull up to 1920'. Lay 100' cement plug from 1920-1820'.

6. Pull up to 960'. Lay 100' cement plug from 960-860'. **Perf / 860'**

7. Lay down remainder of 4 1/2" casing. **Pump 50' sac cement down 10 3/4 x 7 5/8 annulus.**

8. Lay 10' cement plug in top of 7 5/8 casing.

9. Cut off casing and wellhead below ground level. Install dry hole marker. Remove all surface pipe and equipment from location R & R location as per state regulation

Approval Granted providing work
is complete by **7-10-08**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE *Ken McKinney*

TITLE Production Manager

DATE 03/25/2008

Type or print name Ken McKinney

E-mail address: KMcKinney@Grynberg.com

Telephone No. 303-850-7490

For State Use Only

APPROVED BY *Gerry Guye*

TITLE Gerry Guye
Compliance Officer

DATE

APR 10 2008

Conditions of Approval (if any):

QUICKSILVER

BRIDGEPORT, TEXAS 76426
MOBILE 817/994-9593

PHONE A/C 817/683-2194 or 683-4093

P.O. BOX 366
FAX 817/466-3277

COMPANY McDermott 30 Com No 1

DATE 3-25-08

PHONE

WELL NO. 1

LEASE McDermott

FIELD Abc

