

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-22826
1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator SDX Resources, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 5061, Midland, TX 79704		7. Lease Name or Unit Agreement Name State 32 Com
4. Well Location Unit Letter <u>B</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>32</u> Township <u>19S</u> Range <u>28E</u> NMPM <u>Eddy</u> County		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <u>020451</u>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		10. Pool name or Wildcat Burton Flat, Strawn, N (Gas)
Pit or Below-grade Tank Application ☐ or Closure ☐		
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ P AND A ☐ CASING/CEMENT JOB ☐ OTHER: ☐
--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Current:
11-3/4" 42# H40 @ 360'. Cmt w/375 sx. Circ.
8-5/8" 24# K55 & S80 @ 2608'. Cmt w/1150 sx. Circ.
4-1/2" 11.6# & 13.5# N80 & K55. Set @ 11135'. Cmt w/460 sx. DV tool @ 7120'. TOC 5210' by TS
Perfs: 10596-10930'. CIBP @ 10520' w/30' cmt
Perfs: 9516-53'. Acidized & fraced.
CIBP @ 9416'. Capped w/35' cmt.

Propose to P&A well as follows: Circ mud laden fl from PBTD. 25 sx plug @ 8649' (Wolfcamp).
100' plug 3070' - 7170'. Cut & pull csg from 5200'. 100' stub plug 50' in/out & tag.
25 sx plug 4450' (Bone Spring). Shoe plug 2558' - 2658' & tag.
Shoe plug 560' - 310' & tag. 60' Surface plug

Notify OCD 24 hrs. prior to any work done.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Bonnie Atwater TITLE Regulatory Tech DATE 5/30/08
Bonnie Atwater batwater@sdresources.com 432-685-1761
Type or print name E-mail address: Telephone No.
For State Use Only

APPROVED BY: Phil Hankins TITLE Complia Officer DATE 6/3/08
Conditions of Approval (if any):