Form 3160-5 (April 2004)

1. Type of Well Oil Well

1850' FNL 1650' FEL Sec 29, T17S, R28E, Unit G

3a Address

2. Name of Operator SDX Resources, Inc.

PO Box 5061, Midland, TX 79704

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-	ARTESIA_	
	·	

FORM APPROVED



SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

Gas Well

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

	OM B No. 1004-0137 Expires: March 31, 2007					
5. Lease Serial No.						
	NMLC-046250(B)					
	6. If Indian, Allottee or Tribe Name					
	7. If Unit or CA/Agreement, Name and/or No.					
	8. Well Name and No.					
	Williams B Federal #6 (27688)					
	9. API Well No.					
	30-015-35900					
	10. Field and Pool, or Exploratory Area					
	Artesia, GL-YE (96830)					
	11. County or Parish, State					

Eddy Co., NM

12. CHECK AI	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, REPORT, O	R OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity ✓ Other Spud & set esg.			

3b. Phone No. line

432-685-1761

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud 12-1/4" hole 5/28/08. Drill to 465'. Run 14 jts 8-5/8" J-55 24# esg. Set @ 457'. Cmt w/100 sx Cl H & 375 sx Cl C cmt. Did not circ. Cmt @ 30' & holding. Witnessed by BLM Kent Caffel. WOC total of 36 hrs. Begin drlg 7-7/8" hole. Reached TD of 3570' on 6/4/08. Run OH logs. Run 88 jts 5-1/2" J-55 14# ST&C csg, Set @ 3555'. Cmt w/350 sx 35/65/6/C + 400 sx Cl C. Circ 52 sx to pit.

Rig released 6:00 a.m. 6/5/08.						
кід кеказей оли я.ш. о/э/ов.				ACCEPTED END DECOD		
Currently: WO Completion.				ACCEPTED FOR RECOR		
			Г			
				4 2 2000		
		!		JUL 1 2 2008		
				1//		
			عار	- CMI		
			Zübi	AU OF LAND MANAGEMENT		
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	ı			ARLSBAD FIELD OFFICE		
Bonnie Atwater	Title A	gent	·			
Signature Bennie Stuater	Date		06/25/2008			
THIS SPACE FOR FEDERAL	ORS	TATE OFFIC	EUSE			
Approved by	1	itle		Date		
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject le	1	Office				
which would entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						

(Instructions on page 2)

