

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

S

5 Lease Serial No.

NM-78213

6 If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐

Oil Well

☐

Gas Well

☒

Other P&A

AUG 19 2008

2 Name of Operator

Yates Petroleum Corporation

OCD-ARTESIA

3a. Address

105 S. 4th Str., Artesia, NM 88210

3b Phone No (include area code)

575-748-1471

4 Location of Well (Footage, Sec., T, R., M., OR Survey Description)

990'FSL & 2310'FEL of Section 3-T22S-R24E (Unit O, SWSE)

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Walt Canyon AMA Federal #1

9. API Well No

30-015-10305

10 Field and Pool or Exploratory Area

Indian Basin; Upper Penn Assoc.

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐

Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice

☐

Acidize

☐

Alter Casing

☐

Casing Repair

☐

Change Plans

☐

Convert to Injection

☐

Deepen

☐

Fracture Treat

☐

New Construction

☒

Plug and Abandon

☐

Plug Back

☐

Production (Start/Resume)

☐

Reclamation

☐

Recomplete

☐

Temporarily Abandon

☐

Water Disposal

☐

Water Shut-Off

☐

Well Integrity

☐

Other

13 Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

6/9/08 Set a CIBP at 6750'.

6/10/08 Spotted 25 sx cement at 6250'. Perforated at 5600'.

6/11/08 Pumped 55 sx cement through perfs at 5600'. WOC and tagged at 5400'. Perforated at 4254'. Pumped 50 sx cement and WOC.

6/12/08 Tagged at 3700'. Called BLM and plug OK. Perforated at 3650'. Pumped 50 sx cement and WOC. Tagged at 3423'. Perforated at 448'. Circulated 140 sx cement to surface.

6/15/08 Fill casing to surface with 20 sx cement. Cut off wellhead. Installed dry hole marker. **WELL IS PLUGGED AND ABANDONED.**

ACCEPTED FOR RECORD

AUG 19 2008

Gerry Guye, Deputy Field Inspector

NMOCD-District II ARTESIA

14 I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Tina Huerta

Title Regulatory Compliance Supervisor

Signature

Date

June 17, 2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease, which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

ACCEPTED FOR RECORD	
AUG 16 2008	
BUREAU OF LAND MANAGEMENT	
CANNESAD FILED OFFICE	