

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87401

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised March 25, 1999

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-015-30947

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Texmack 36 State Com

SUBDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Chevron USA Inc

3. Address of Operator

15 Smith Rd, Midland, TX 79705

4. Well Location

Unit Letter J : 1980 feet from the South line and 1880 feet from the East line

Section 36 Township 16-S Range 31-E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

4104

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24 hrs prior to MI and RU.
2. Set 5 1/2 CIBP @ 12,325, spot 20sx, plug 12,325-12,125 (Morrow) WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
4. Spot 30sx, plug 9100-8800 (DV Tool, Wolfcamp). ← 25sx plug @ 12014'
5. Spot 30sx, plug 7400-7100 (ABO). 5000 - 5300
6. Spot 30sx, plug 4600-4300 (8 5/8 Shoe) WOC Tag.
7. Spot 45sx, plug 2300-1900 (Yates, B-Salt) WOC Tag.
8. Spot 30sx, plug 1100-800 (T-Salt) WOC Tag.
9. Spot 65sx, plug 600-Surf (11 3/4 Shoe, Surf) WOC Tag.
10. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE B.R. Bledsoe TITLE HES Specialist

DATE 10/23/2003

Type or print name G.R. Bledsoe

(This space for State use)

Telephone No. (432) 687-7153

APPROVED BY [Signature]

TITLE

DATE

Conditions of approval, if any:

APPROVED OCT 29 2003

(STRING CSNG)

LEASE NAME Texmac 3 1/2 STATE TX

WELL # 3

FROM 1980 NSL 1980 EWL

TD 12.1660 FORMATION @ TD Morrow

PBTD FORMATION @ PBTD

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	11 3/4	550	SURF	CIRC
INTMED 1	8 5/8	4543	SURF	CIRC
INTMED 2				
PROD	5 1/2	12650	SURF	CIRC.

	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					

	CUT & PULL		TOP - BOTTOM
INTMED 1		PERFS	12,373 - 12,402
INTMED 2		OPENHOLE	
PROD			

*REQUIRED PLUGS DISTRICT

	PLUG	TYPE PLUG	SACKS CEMENT	DEPTH
RUSTLER (ANHYD)	1	CIBP	20	12325
YATES	2	DV TOOL	30	9100
QUEEN	3	ABO	30	7400
GRAYBURG	4	8512 S	30	4600
SAN ANDRES	5	YATES	45	2300
	6	T-SALT	30	1100
CAPITAN REEF	7	1134 S	65	600
DELAWARE				
BELL CANYON				
CHERRY CANYON				
BRUSHY CANYON				
BONE SPRING				
GLORIETA				
BLINBRY				
TUBB				
DRINKARD				
ABO				
WC				
PENN				
STRAWN				
ATOKA				
MORROW				
MISS				
DEVONIAN				

