State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION			WELL API NO.	
DISTRICT II		2040 Pacheco St. Santa Fe, NM 87505		512
P.O. Drawer DD, Artesia, NM 88210		•	sIndicate Type of Lea	יאסע ו
<u>DISTRICT III</u>			«State Oil & Gas Lea	STATE XX FEE
1000 Rio Brazos Rd., Aztec, NM 87410			K-851	
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			Lease Name or Uni	•
(FORM C-1	101) FOR SUCH PROPOSALS.)	*4 *	 State 19 (RECEIVED
OIL GAS XX OTHER WELL XX		July 13 C	NOV - 7 2003	
*Name of Operator		₅Well No.	OCD-ARTESIA	
Pogo Producing Company Address of Operator			Pool name or Wildo	zat
P. O. Box 10340, Midland, TX 79702-7340				e Spring, North
4Well Location	Feet From The South	Line and 660	Feet From The	West Line
Section 19	Township 20S	Range 27E	NMPM E	ddy County
	••Elevation (Show whether to 328	OF, RKB, RT, GR, etc.)		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
			SEQUENT RI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. XX	PLUG AND ANBANDONMENT
PULL OR ALTER CASING CASING TEST AND CEM			IENT JOB	
OTHER:		OTHER:		
uDescribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
•				
Spud & Set Surface Csg – MIRU Patterson #142. Spud well @ 00:15 hrs 08/06/03. Drld 17-1/2" hole to 450'. TD reached @ 17:30 hrs 08/06/03. Ran 10 jts 13-3/8" 48# H-40 ST&C csg. TPGS @ 450'. Cmt'd w/ 250 sks Premium Plus Cl "C" + 2% CaCl2 followed				
by 450 sks 65:35 POZ "C" tail w/ 200 sks Cl "C" + 2% CaCl2. Plug down @ 01:30 hrs 08/07/03. Cmt did not circ. Called Mike				
Bratcher w/ NMOCD. Ran temp survey. TOC 25' ft from surface. Cmt w/ 1" pipe w/ 130 sks Cl "C" w/ 3% CaCl2. Circ 10 sks to surface. WQC. Make cut-off. Weld on WH. NU BOP's & test ok.				
Surface. WGC. Make cut-off. Weld off WH. NO BOY'S & test ok.				
Intermediate Csg - Drld 12-1/4" hole to 3000'. TD reached @ 22:00 hrs 08/11/03. Ran 71 jts 9-5/8" 40#, 43.5# & 53.5#, N-80, J-55				
& P-110 LTC & STC csg. Cmt'd 1 st stage w/ 400 sks Premium Plus @ 12.4 ppg followed by 200 sks Cl "C" + 1% CaCl2 @ 14.8 ppg. Circ 117 sks to surface. Cmt'd 2 nd stage w/ 275 sks Premium Plus @ 12.4 ppg followed by 100 sks Cl "C" + 1% CaCl2 @ 14.8				
ppg. Circ 232 sks to surface. WOC 24 hrs. Make cut-off. Weld on WH. NU BOP's & test ok.				
) we c	Time ?		·	
	0			
I hereby certify that the information above is	true and complete to the best of my kno	wledge and belief.		
SIGNATURE Cathy UU	izht	тпье Sr. Operat	ion Tech	DATE 10/31/03
TYPE OR PRINT NAME Cathy	Wright	432-685-	8100	TELEPHONE NO.
(This space for State Use)				NOV 1 2 2003
APPROVED BY	records only	TITLE		DATE