## OCD-ARTESIA

Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

LC 029420-B SUNDRY NOTICES AND REPORTS ON WELLS OCD-ARTES Abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. Type of We Oil Well Gas Well Other 8. Well Name and No. Panther Federal #1 2. Name of Operator V-F Petroleum Inc. 9. API Well No. 30-015-29142 3a. Address 3b. Phone No. (include area code) P.O. Box 1889, Midland, Texas 79702 432-683-3344 10. Field and Pool, or Exploratory Area **Shugart North Bone Spring** 4. Location of Well (Footage, Sec., T, R, M., or Survey Description) 11 County or Parish, State Unit K, 1,830' FSL, 2,130' FWL, Section 33, T-17-S, R-31-E **Eddy County, New Mexico** 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Water Shut-Off Deepen Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Recomplete Casing Repair New Construction Other Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection ✓ Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 11/13/08 TOH with tubing packer. Rig up BJ Services. Sand frac Bone Spring perforations 7,878' - 7,888' with 89,796 gallons lightning gel KCl water plus 11/14/08 200,315# 16/30 white sand. Set composite bridge plug at 7,660'. Perforate Bone Spring zone 7,410' - 7,420', 21 holes. Acidize with 2,000 gallons 15% NeFe HCl acid. Sand frac with 91,266 gallons lightning gel 2% KCl water plus 211,206# 16/30 white sand. 11/15/08 to 11/18/08 Flow back frac water. 11/19/08 Drill out CIBP. Start putting well on rod pump. 11/21/08 Well on pump. 1 1/4" pump set 7,901'. 2009 JAN ACCEPTED FOR RECORD ÁU OF LAND MANAGEMENT ARLSBAD FIELD OFFICE I hereby certify that the foregoing is true and correct Name (Printed/Typed) Gerry Guye, Deputy Field Ide Poste President S.K. Lawlis NMOCD-District II ARTESIA 12/22/2008 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or représentations as to any matter within its jurisdiction

Ĺ

which would entitle the applicant to conduct operations thereon.