FEB - 4 2009

O. J. Co. O. C. W. A Let Dissolut	A		L FD . 7009	
Submit 3 Copies To Appropriate District	State of New Me	XICO	ŀ	Form C-103
Office	Energy, Minerals and Natur	ral Resources		June 19, 2008
District I 1625 N. French Dr., Hobbs, NM 88240		WE	LL API NO.	
District II	,	20.0	115-31530	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION			
District III	1220 South St. Fran	cic Dr	ndicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		" 1	STATE 🔀 FEE	
District IV	Santa Fe, NM 87	505 6. S	tate Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				ļ
87505		Comment of the Commen		
	ICES AND REPORTS ON WELLS	7.1	ease Name or Unit Agree	ment Name
	SALS TO DRILL OR TO DEEPEN OR PLU		RON STATE	
	CATION FOR PERMIT" (FORM C-101) FO		KONSTATE	l
PROPOSALS.)				
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other		8. V	8. Well Number #1	
		0.6	0 00mm N 1 055000	
2. Name of Operator		9. C	OGRID Number 255333	
LIME ROCK RESOURCES A,	L.P.			
3. Address of Operator		10.	10. Pool name or Wildcat	
c/o Mike Pippin LLC, 3104 N. Sul	llivan, Farmington, NM 87401	Arte	Artesia: Queen-Grayburg-San Andres (3230) &	
FF	, , , , , , , , , , , , , , , , , , ,		NE Red Lake: Glorieta-Yeso (96836)	
4 337 11 7			(3)	
4. Well Location				İ
Unit Letter C	530 feet from the SOUTH	I line and <u>1650</u>	feet from the WEST	[line
Section 32	Township 17-S	Range 28-E NMP	M Eddy County	
Section 32			W Eddy County	
4.5	11. Elevation (Show whether DR,	KKB, RI, GR, etc.)		
	3678' GL			
12 Charle	Ammanuiata Day ta Indiaata M	otive of Notice Dome	unt au Othau Data	
12. Check	Appropriate Box to Indicate Na	ature of Notice, Repo	on or Omer Data	
	TENTION TO	0110000	LIEUT DECONT OF	
	NOTICE OF INTENTION TO: SUE			
NOTICE OF IN			UENT REPORT OF	•:
NOTICE OF IN PERFORM REMEDIAL WORK □	PLUG AND ABANDON [SUBSEQ REMEDIAL WORK		-: CASING □
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING	CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING	☐ ALTERING GOPNS.☐ PANDA	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING GOPNS.☐ PANDA	CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING	☐ ALTERING GOPNS.☐ PANDA	CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRILLING	☐ ALTERING GOPNS.☐ PANDA	CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER:	☐ ALTERING GOPNS.☐ PANDA ☐	CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER:	☐ ALTERING GOPNS.☐ PANDA ☐	CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all p	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give	ALTERING OPNS. P AND A pertinent dates, including	CASING Cas
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost of starting any proposed w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give	ALTERING OPNS. P AND A pertinent dates, including	CASING Cas
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all p	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give	ALTERING OPNS. P AND A pertinent dates, including	CASING Cas
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or composed or composed was a composed or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give a Completions: Attach we	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of propos	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost starting any proposed wor recompletion. Lime Rock Resources would like to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commi	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give e Completions: Attach we have a completion of the com	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost starting any proposed wor recompletion. Lime Rock Resources would like to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give e Completions: Attach we have a completion of the com	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost starting any proposed wor recompletion. Lime Rock Resources would like to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commi	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give e Completions: Attach we have a completion of the com	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost starting any proposed wor recompletion. Lime Rock Resources would like to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commi	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give e Completions: Attach we have a completion of the com	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost starting any proposed wor recompletion. Lime Rock Resources would like to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commi	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give e Completions: Attach we have a completion of the com	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Com 13. Describe proposed or compost starting any proposed wor recompletion. Lime Rock Resources would like to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commi	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: pertinent details, and give e Completions: Attach we have a completion of the com	ALTERING OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE THE Remove RBP & Common of starting any proposed was or recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Discrete proposed was performed by the proposed by th	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Multiple Manager	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give the Completions: Attach with the completion of the completion of the completion of the completion of the commingled as per least the commingle of the commingle	ALTERING B OPNS. P AND A pertinent dates, including rellbore diagram of proposities perfs (2420'-49') with PC-1096.	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comforting any proposed or comport starting any proposed wor recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per DF	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Multiple Miningle Min	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give the Completions: Attach with the Attach with the Completion of the Existing San And face commingled as per lease Date: Solution 1	ALTERING GOPNS. P AND A pertinent dates, including rellbore diagram of proposedres perfs (2420'-49') with PC-1096.	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comforting any proposed or comport starting any proposed wor recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per DF	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Multiple Manager	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give the Completions: Attach with the Attach with the Completion of the Existing San And face commingled as per lease Date: Solution 1	ALTERING GOPNS. P AND A pertinent dates, including rellbore diagram of proposedres perfs (2420'-49') with PC-1096.	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comforting any proposed or comport starting any proposed wor recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per DF	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Multiple Miningle Min	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give the Completions: Attach with the Attach with the Completion of the Existing San And face commingled as per lease Date: Solution 1	ALTERING GOPNS. P AND A pertinent dates, including rellbore diagram of proposedres perfs (2420'-49') with PC-1096.	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comforting any proposed or comport starting any proposed wor recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per DF	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Multiple Miningle Min	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give the Completions: Attach with the Attach with the Completion of the Existing San And face commingled as per lease Date: Solution 1	ALTERING GOPNS. P AND A pertinent dates, including rellbore diagram of proposedres perfs (2420'-49') with PC-1096.	CASING Casing cases and cases cases completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Common of starting any proposed was or recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Discourse Spud Date: 5/2/01 I hereby certify that the information	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commit IC-3689. The production will be sure Drilling Rig above is true and complete to the be	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give e Completions: Attach we have a completion of the existing San And face commingled as per lease Date: Release Date: 5/16 st of my knowledge and lease Date.	ALTERING B OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with PC-1096.	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comforting any proposed or comport starting any proposed wor recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per DF	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commit IC-3689. The production will be sure Drilling Rig above is true and complete to the be	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give the Completions: Attach with the Attach with the Completion of the Existing San And face commingled as per lease Date: Solution 1	ALTERING GOPNS. P AND A pertinent dates, including rellbore diagram of proposedres perfs (2420'-49') with PC-1096.	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE TO THER: Remove RBP & Common of starting any proposed we consider of starting any proposed we consider of the starting and the starting	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & committed IC-3689. The production will be sure Drilling Rig above is true and complete to the bear TITLE Petrole	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	ALTERING GOPNS. PAND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with PC-1096.	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE TO THER: Remove RBP & Common of starting any proposed we consider the completion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Discrete Spud Date: 5/2/01 I hereby certify that the information SIGNATURE Mike Pipping Type or print name Mike Pipping Spud Date: Mike Pipping Mike Pipping Spud Date: Mike Pipping Mike Pipping Mike Pipping Mike Pipping Spud Date: Mike Pipping Mike Pipping Mike Pipping Spud Date: Mike Pipping Mike Pipping Mike Pipping Spud Date: Mike Pipping Mike Pipping Spud Date: Mike Pipping Mike Pipping Mike Pipping Spud Date: Mike	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & committed IC-3689. The production will be sure Drilling Rig above is true and complete to the beautiful TITLE Petrole	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	ALTERING B OPNS. P AND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with PC-1096.	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE TO THER: Remove RBP & Common of starting any proposed we consider of starting any proposed we consider of the starting and the starting	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & committed IC-3689. The production will be sure Drilling Rig above is true and complete to the bear TITLE Petrole	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	ALTERING GOPNS. PAND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with PC-1096.	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE TOWNHOLE COMMINGLE TOWNHOLE COMMINGLE TOWNHOLE Remove RBP & Common of starting any proposed we not recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Discrete Spud Date: 5/2/01 I hereby certify that the information SIGNATURE Mike Pipping For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Deleted operations. (Clearly state all poork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commit IC-3689. The production will be sure Drilling Rig above is true and complete to the beat TITLE Petrolete E-mail address:	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	DATE 1/29/09 ALTERING P AND A P AND A Pertinent dates, including relibore diagram of proposed propo	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comfort Starting any proposed or comfort starting any proposed with or recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Difference of Starting Star	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Detected operations. (Clearly state all pork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & committed IC-3689. The production will be sure Drilling Rig above is true and complete to the bear TITLE Petrole	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	ALTERING GOPNS. PAND A pertinent dates, including rellbore diagram of proposed res perfs (2420'-49') with PC-1096.	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE TOWNHOLE COMMINGLE TOWNHOLE COMMINGLE TOWNHOLE Remove RBP & Common of starting any proposed we not recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Discrete Spud Date: 5/2/01 I hereby certify that the information SIGNATURE Mike Pipping For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Deleted operations. (Clearly state all poork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commit IC-3689. The production will be sure Drilling Rig above is true and complete to the beat TITLE Petrolete E-mail address:	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	DATE 1/29/09 ALTERING P AND A P AND A Pertinent dates, including relibore diagram of proposed propo	estimated date sed completion the existing
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Remove RBP & Comfort Starting any proposed or comfort starting any proposed with or recompletion. Lime Rock Resources would like to Yeso perfs (3456'-3534') as per Difference of Starting Star	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL mingle Deleted operations. (Clearly state all poork). SEE RULE 1103. For Multiple remove the RBP @ 3400' & commit IC-3689. The production will be sure Drilling Rig above is true and complete to the beat TITLE Petrolete E-mail address:	REMEDIAL WORK COMMENCE DRILLING CASING/CEMENT JOB OTHER: Pertinent details, and give a Completions: Attach we have a completion of the existing San And face commingled as per left stof my knowledge and left st	DATE 1/29/09 ALTERING P AND A P AND A Pertinent dates, including relibore diagram of proposed propo	estimated date sed completion the existing

Mh