Form 3160-5

(September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires January 31, 2004

5. Lense Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS				NM 064200
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6 If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No
1. Type of Well X Oil Well Gas Well Other				8. Well Name and No. WADI 15 FEDERAL #1
2 Name of Operator				WADI 15 FEDERAL #1
CIMAREX ENERGY CO. OF COLORADO ATIN: ZENO FARRIS			9. API Well No.	
3a. Address	Phone No (include area	r code)	30-015-29764	
P.O. BOX 140907, IRVING, TEXAS 7501 4 Location of Well (Footage, Sec., T. R., M., or Survey 1	972.443.6489		10. Field and Pool, or Exploratory Area	
UNIT LETTER C			BLACK RIVER DELAWARE	
660'' FNL & 1,980' FWL				11. County or Parish, State
SEC. 15, T-24-S, R-26-E			EDDY NM	
12. CHECK APPROPRIATE	BOX(ES) TO INDIC	ATE NATURE OF N	OTICE, REP	
TYPE OF SUBMISSION TYPE OF ACTIO			- OF ACTION	
Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off
	Alter Casing	Fracture Treat	Reclamatio	on Well Integrity
X Subsequent Report	Casing Repair	New Construction	Recomplet	
	Change Plans	X Plug and Abandon		
Final Abandonment Notice		-		ly Abandon
	Convert to Injection	Plug Back	Water Disp	oosal
13 Describe Proposed or Completed Operation (clearl If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. It testing has been completed. Final Abandonment if determined that the final site is ready for final inspec-	plete horizontally, give subst formed or provide the Bor If the operation results in a Notices shall be filed only a	urface locations and measu id No. on file with BLM/E multiple completion or rec	arcd and true ver SIA Required s completion in a r	rtical depths of all pertinent markers and zones, subsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once
02/05/09: RIH W/ TBG, & TAG EXIST CIRC. WELL W/ PXA MUD;	SET 5-1/2" CIBP @	2,700'.	PA 25 SX.	CMT. PLUG @ 3,412' PER BIM;
02/06/09: MIX & FUMP A 25 SX. CMT. PLUG @ 2,700'-2,500' (CALC.).				
02/09/09: MIX & FUMP A 25 SX. CMT. FLUG (1,965'-1,765'(CALC.); MIX & FUMP A 25 SX. CMT. FLUG (1,475'; WOC & TAG TOP OF CMT. FLUG (1,223'.				
			n mmaa a a	AGI. MEV C TEMP & 1E 69
02/10/09: MIX & PUMP A 35 SX. CMT. PLUG @ 680'; WCC & TAG TOP OF CMT. PLUG @ 248'; MIX & PUMP A 15 SX. CMT. SURF. PLUG @ 63'-3'; DIG CUT & CUT OFF WELLHEAD 3' B.G.L. & WELD ON DRY HOLE MARKER.				
CIL. DOLL, 1200 C OF S / 220 COL C OF SIL MARKETS S 2.0.41 C FEEL ON DIC 1200 I 1200 C				
WELL PLUGGED AND ABANDONED 02/11/	os. Accepte	d for record		
List		Appr Liabi	oved as to plugging of the well bore. lity under bond is retained until	
				ice restoration is completed.
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		Title		
Name (Printed/Typed) DAVID A. EYLER		AGENT		
Dans A. E	2	Date 02/12/09		APPROVED
THE	S SPACE FOR FEDER	RAL OR STATE OFF	ICE USE	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				

Title Approved by 5 2009 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department of representations as to any matter within its jurisdiction. States any false, fictifious or fraudulent statements or representations as to any matter within its jurisdiction.

David Eyler

From:

jeff kester [royaltyws@msn.com]

Sent:

Wednesday, February 11, 2009 2:26 PM

To:

Gary McDaniel; Leslie White; Trista Well Service; Royalty Office; Sheila; Austin McDaniel;

David Eyler

Subject:

Wadi 15 Fed #1

Cimarex Daniel

2/4/09

Ru nipple up bop, unset tac, pooh w/82 jts 2 7/8 tbg, tallied back in hole.

2/5/09

Brought 40 jts from last loc. Tripped in hole and tagged @3412", plug added by blm circ. Mud', spot 25 sxs cmt as instructed by BLM, pooh, tripped back in hole with cibp and set @2700', cwi SDFD

6 hrs rig

25 sks cement

2/9/09

Spot mud, spot 25 sxs @2700', pooh to 1965', spot 25 sxs, pooh to 1475', spot 25 sxs, pooh, sdfn

2/10/09

Tripped in hole tg @1223', pooh to 680', spot 35 sxs, pooh. Woc got to windy, sdfn

2/11/09Tripped in hole and tg@248', pooh to 63', spot 15 sxs to surface, rig down, cut of wellhead, welded Id marker, removed anchors.

Well complete

Sent from my Verizon Wireless BlackBerry

Accepted for record NMOCD