2009 RM

		IVI. UII CON	S. DIV-DI	St. 🐔	_	
,	UNITED STATES DEPARTMENT OF THE BUREAU OF LAND MAN NOTICES AND REF		VM 8821	TO Lease Serie NM-927	PORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 Il No.	MAY 132
	nis form for proposals to ell. Use Form 3160-3 (A			6. If Indian	, Allottee or Tribe Nan	ie
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Oil Well D	Gas Well 🗆 🔲 Other			8. Well Nan	ne and No.	
2. Name of Operator Primero Operating, Inc.				Fajita Federal Com #1 9. API Well No.		
3a Address PO Box 1433, Reswell, NM 88	3b. Phone No. (inchide 575 622 1001	area code)	30 005 60190 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Buffalo Valley; Atoka Gas 11. County or Parish, State		
T15S, R27E, Section 10, 1650' Fsl and 990' FEL				Chaves, NM		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RI	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Star	rt/Resume)	Water Shut-Off Well Integrity Other	
Subsequent Report Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Ab	andon		
	Convert to Injection	Pług Back	Water Disposal			
Attach the Bond under which t following completion of the im	ectionally or recomplete horizontall he work will be performed or provi volved operations. If the operation hal Abandonment Notices shall be	ly, give subsurface location ide the Bond No. on file w results in a multiple comp	ns and measured and true with BLM/BIA. Require detion or recompletion in	e vertical depth ed subsequent r n a new interva	ns of all pertinent mark reports shall be filed wi II, a Form 3160-4 shall	ers and zones. ithin 30 days be filed once
4/2/09 Finish POH w/ tub Perforate squeeze 4/3/09 Pump 40 sx Class (PuB up and pump POH to 1590', MI POH WOC 2 hrs a RIH and pump 40 WOC 2 hours, RIF RIH w/ 2 jts tubing RDMO Pulling Un	nmary: 1. CIBP @ 8178' w/ 3	Set CIBP at 8178' and es each). RIH w/ 5500' ation in and out of 5 1/2 renlation in and out of 4 holes @ 1607', Pump ne. Perforate 4 squeeze d circulateion in and out of le and out of 5 1/2" cas	dump 35' cement on ' of tubing. 2" casing 5 1/2" casing ed 40 sx Class C ceme e holes each at 378' a ut of 5 1/2" ing with cement, circ	ent w/ good o nd 50'. zalate 10 sx to 500', 3. 40 sx	o surface. Class C from 3450	to 3550'
The location is cleared of 14. Thereby certify that the fore	junk and a dry hole marker h	as been installed. The	location will be reme	diated per B	LM instruction.	
Name (Printed/Typed) Phelps White	going is true and correct	Title P	resident			
Signature 2		Date	4-8-09			
	THIS SPACE FOR	FEDERAL OR S	TATE OFFICE	USE		
Approved by /S/D/	AVID R. GL		ROLEUM ENG	INEER I	Date APR	1 5 2009
Conditions of approval, if any, are certify that the applicant holds legatively which would entitle the applicant.	il or equitable title to those rights i		Office			

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon.



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

APPROVED AS TO PLUGGING OF THIS WELL BORE. LIABILITY UNDER BOND IS RETAINED UNTIL SURFACE RESTORATION IS COMPLETED